

~~SAFEGUARDS INFORMATION~~

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-341/86004(DRSS)

Docket No. 50-341

License No. NPF-33

Safeguards Group IV

Licensee: Detroit Edison Company  
2200 Second Avenue  
Detroit, MI 48226

Facility Name: Enrico Fermi Atomic Power Plant

Inspection At: Plant Site

Inspection Conducted: January 27-30, 1986

Date of Previous Physical Security Inspection: November 12 through  
December 27, 1985

Type of Inspection: Reactive Physical Security Inspection

Inspector: G. L. Pirtle  
G. L. Pirtle  
Physical Security Inspector

2/20/86  
Date

Approved By: J. R. Creed  
J. R. Creed, Chief  
Safeguards Section

2/20/86  
Date

Inspection Summary

Inspection on January 27-30, 1986 (Report No. 50-341/86004(DRSS))

Areas Inspected: Included Management Effectiveness - Security Program; Security Organization; Alarm Stations; and Access Control - Personnel. The inspection involved 31 inspector-hours by one NRC inspector.

Results: No violations of NRC requirements were noted in the areas inspected. An unresolved item pertaining to a portion of a vital area barrier was noted and will be sent to NRC, HQ for resolution. Supervision and performance of the uniformed force appeared adequate. Morale of the GTOC security staff appears to warrant security management attention. The licensee committed to complete an audit of their zone deviation access control program by February 10, 1986. Progress was noted in correcting the adverse trends pertaining to excessive compensatory measures, access control personnel errors, and timely maintenance support for security equipment. Finally, clarity and resolution for a closed circuit television monitor required improvement.

(Details: UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure contains  
SAFEGUARDS INFORMATION  
Upon separation this  
page is Decontrolled

B602250021 B60220  
PDR ADOCK 05000341  
G PDR

~~SAFEGUARDS INFORMATION~~