



Log # TXX-88645
File # 10110
903.11
Ref. # 10CFR50.55(e)

August 31, 1988

William G. Council
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
UNQUALIFIED LIMITORQUE ACTUATORS
SDAR: CP-87-132 (SUPPLEMENTAL REPORT)

Gentlemen:

On January 5, 1988, TU Electric letter, logged TXX-88027, provided notification that the deficiency involving unqualified Limitorque actuators was reportable under the provisions of 10CFR50.55(e). Our latest report on this issue, logged TXX-88374, was submitted March 31, 1988. This report is submitted to update the corrective action completion schedule.

Unit 1 corrective actions have been rescheduled for completion by December 14, 1988. The schedule for Unit 2 remains unchanged.

Very truly yours,

W. G. Council
W. G. Council

VPC/gj

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8809060392 880831
PDR ADOCK 05000445
S PDC

*IE27
/10*