AUG 2 4 1988

Docket Nos. 50-413, 50-414 License Nos. MPF-35, NPF-52

Duke Power Company LATTN: Mr. H. B. Tucker, Vice President Nuclear Production Department 422 South Church Street Charlotte, NC 28242

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-413/88-28 AND 50-414/88-28

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by P. Stoddart on July 25-29, 1988. The inspection included a review of activities authorized for your Catawba facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

D. M. Collins

Douglas M. Collins, Chief Emergency Preparedness and Radiological Protection Branch Division of Radiation Safety and Safeguards

official

.

PNU

8809070017 880824

PDR ADOCK 05000413

Enclosure NRC Inspection Report

cc w/encl: VI. B. Owen, Station Manager

bcc: (See page 2)

Duke Power Company

. ...

1

bcc w/encl: VK: N. Jabbour, NRR NRC Resident Inspector DRS, Technical Assistant Document Control Desk State of South Carolina

RII MS PStoddart:sh 08/13/88



RII TPeebles 08/ 7/88