

September 1, 1988

Docket Nos.: 50-321
50-366

Mr. W. G. Hairston, III
Senior Vice President -
Nuclear Operations
Georgia Power Company
P. O. Box 4545
Atlanta, Georgia 30302

Dear Mr. Hairston:

SUBJECT: PLAN FOR IGSCC INSPECTION, HATCH 1 REFUELING OUTAGE
(TACS 68691)

Your letter of June 30, 1988, provided your response to Generic Letter 88-01 for Plant Hatch and further provided your plan for inspection of the Unit 1 austenitic stainless steel piping during the fall 1988 refueling outage. Several questions have been identified as a result of the review to date of your June 30 letter. These are identified in the enclosure. Your response to these questions is requested as soon as possible in order to enable the staff review to be completed prior to the scheduled start of the outage. In the interest of expediting your response, I forwarded a copy of the questions to your Mr. Heidt via facsimile on August 29, 1988.

Please call me if you have any questions.

Sincerely,

Original Signed By:

8809070030 880901
PDR ADOCK 05000321
G PNU

Lawrence P. Crocker, Project Manager
Project Directorate II-3
Division of Reactor Projects - I/II

Enclosure:
As stated

cc: See next page

DISTRIBUTION

Docket File

- NRC PDR
- Local PDR
- PDII-3 Reading
- S. Varga 14-E-4
- G. Lainas 14-H-3
- D. Matthews 14-H-25
- M. Rood 14-H-25
- L. Crocker 14-H-25
- OGC 15-B-18
- E. Jordan MNBB-3302
- B. Grimes 9-A-2
- ACRS (10) H-1016

HATCH PLANT FILE

- PDII-3
- MRood
- 9/1/88
- PDII-3
- LCrocker:sw
- 9/1/88
- PDII-3
- CDMatthews
- 9/1/88

DFC 1/19

ML *ML*

Mr. W. G. Hairston, III
Georgia Power Company

Edwin I. Hatch Nuclear Plant,
Units Nos. 1 and 2

cc:

G. F. Trowbridge, Esq.
Shaw, Pittman, Potts and Trowbridge
2300 N Street, N. W.
Washington, D.C. 20037

Mr. R. P. McDonald
Executive Vice President -
Nuclear Operations
Georgia Power Company
P.O. Box 4545
Atlanta, Georgia 30302

Mr. L. T. Gucwa
Engineering Department
Georgia Power Company
P. O. Box 4545
Atlanta, Georgia 30302

Nuclear Safety and Compliance Manager
Edwin I. Hatch Nuclear Plant
Georgia Power Company
P. O. Box 442
Baxley, Georgia 31513

Mr. Louis B. Long
Southern Company Services, Inc.
P. O. Box 2625
Birmingham, Alabama 35202

Resident Inspector
U.S. Nuclear Regulatory Commission
Route 1, Box 725
Baxley, Georgia 31513

Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 2900
Atlanta, Georgia 30323

Mr. Charles H. Badger
Office of Planning and Budget
Room 610
270 Washington Street, S.W.
Atlanta, Georgia 30334

Mr. J. Leonard Ledbetter, Commissioner
Department of Natural Resources
270 Washington Street, N.W.
Atlanta, Georgia 30334

Chairman
Appling County Commissioners
County Courthouse
Baxley, Georgia 31513

ENCLOSURE

Hatch, Units 1 and 2

Request for Additional Information

Based upon the preliminary review of the GPC response to Generic Letter 88-01, the need for additional information has been identified as follows:

1. Provide justification for the classification of Category A welds in the submittal in Sections C and D.
2. Provide a justification for not identifying any Category G welds in Sections C and D.
3. Provide a description of accuracy of determining the leakage rates by manually monitoring the time between sump pump starts as stated in Section E12.
4. Provide an explanation and justification of averaging leakage over a 24 hour period as stated in Section E12.
5. Provide clarification of the expression "substantive modifications" included in Section E13.