

MAY - 6 1988

In Reply Refer To:
Dockets: 50-313/88-13
50-368/88-13

Arkansas Power & Light Company
ATTN: Mr. Gene Campbell
Vice President, Nuclear
Operations
P.O. Box 551
Little Rock, Arkansas 72203

Gentlemen:

This refers to the inspection conducted by Messrs. H. F. Bundy and T. O. McKernon of this office during the period April 18-22, 1988, of activities authorized by NRC Operating Licenses DPR-51 and NPF-6 for the Arkansas Nuclear One facility, and to the discussion of our findings with Mr. S. M. Quennoz and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection include modifications testing and testing of piping supports and restraints. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspectors. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

151

L. J. Callan, Director
Division of Reactor Projects

Enclosure: (see next page)

RI *for* HFBundy;dp
5/2/88

RI *for* TOMcKernon
5/2/88

C:TPS *for* WCSeidle
5/2/88

D:DRS *for* JLMiHoan
5/2/88

for C:PSA DChamberlain
5/4/88

D:DRP *for* LJCallan
5/5/88

Reconcur *for* WCSeidle
5/6/88

IE01
1/1

Enclosure:
Appendix - NRC Inspection Report
50-313/88-13
50-368/88-13

cc w/enclosure:
Arkansas Nuclear One
ATTN: J. M. Levine, Director
Site Nuclear Operations
P.O. Box 608
Russellville, Arkansas 72801

Arkansas Radiation Control Program Director

bcc to DMB (IE01)

bcc distrib. by RIV:

*RRI
*RPSB-DRSS
Lisa Shea, RM/ALF
*DRP
*RSTS Operator
*G. Dick, NRR Project Manager
*TSS
*H. F. Bundy
*W. C. Seidle

R. D. Martin, RA
*Section Chief (DRP/A)
*RIV File
*MIS System
*Project Engineer, DRP/A
*DRS
H. Scott, Acting EO
*T. O. McKernon

*w/766