

AUG 30 1988

Docket No. 50-20

Massachusetts Institute of Technology  
Research Reactor  
ATTN: Dr. John A. Bernard  
Director of Reactor Operations  
138 Albany Street  
Cambridge, Massachusetts 02139

Gentlemen:

Subject: Inspection No. 50-20/88-03

This refers to the routine safety inspection conducted by Mr. C. Z. Gordon on July 18-20, 1988, of activities authorized by NRC License No. R-37. The inspection findings were discussed with you and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of emergency procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were identified.

No reply to this letter is required. Your cooperation with us is appreciated.

Sincerely,

Original Signed By:  
Ronald R. Bellamy

Ronald R. Bellamy, Chief  
Facilities Radiation Safety  
and Safeguards Branch

Enclosure: NRC Region I Inspection Report 50-20/88-03

cc w/encl: Dr. O. K. Harling, Director of the Reactor Laboratory  
Public Document Room  
Local Public Document Room  
Nuclear Safety Information Center (NSIC)  
Commonwealth of Massachusetts (2)

"OFFICIAL RECORD COPY"

8809070512 880830  
PDR ADOCK 05000020  
G PNU

DEKS  
1/1

AUG 30 1988

bcc w/encl:

Region I Docket Room (with concurrences)  
Management Assistant, DRMA (w/o encl)  
Robert J. Bores, DRSS  
L. Doerflein, Project Inspector, DRP  
R. Blough, Chief, RPS, 3B

*CG*  
Gordon  
8/25/88

Conklin  
8/25/88

Lazarus  
8/29/88

*man*  
Bellamy  
8/29/88

*AM*

*ALP*

Official Record Copy