

CP&L

Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
August 26, 1988

FILE: B09-13510C
SERIAL: BSEP/88-0842

U.S. Nuclear Regulatory Commission
A.TN: Document Control Desk
Washington, DC 20555


10CFR2.201

BRUNSWICK STEAM ELECTRIC PLANT UNITS 1 AND 2
DOCKET NOS. 50-325 AND 50-324
LICENSE NOS. DPR-71 AND DPR-62
UPDATE OF COMMITMENT REFLECTED IN RESPONSE TO
IE INSPECTION REPORT NOS. 50-325/87-32 AND 50-324/87-31

Gentlemen:

In Carolina Power & Light Company's (CP&L) response to the Notice of Violation identified in IE Inspection Report 50-325/87-32 and 50-324/87-31 dated February 9, 1988 (Serial: BSEP/88-0099), a commitment was made to restore the design configuration of the Unit 1 Core Spray Systems. The original planned completion date for this action, which requires installation of the torus suction supply relief valves, 1-E21-FC32A and FC32B, on the Core Spray System loops, was given as July 15, 1988. This action has been completed on the A Core Spray System; however, due to system maintenance planning considerations, the B Core Spray System valve is not expected to be installed until January 31, 1989.

Very truly yours,



J. L. Harness, General Manager
Brunswick Steam Electric Plant

MJP/bvc

Enclosure

cc: Mr. B. C. Buckley
Dr. J. N. Grace
BSEP NRC Resident Office

8809030053 880826
PDR ADOCK 05000324
Q PDC

IE01
1/0