

yellow

MAY 6 1988

Docket Nos. 50-413, 50-414
License Nos. NPF-35, NPF-52

Duke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-413/88-16 AND 50-414/88-16

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by P. T. Burnett on April 18-22, 1988. The inspection included a review of activities authorized for your Catawba facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

ORIGINAL SIGNED BY
ALAN R. HERDT

Alan R. Herdt, Chief
Engineering Branch
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl:
J. W. Hampton, Station Manager

bcc: (See page 2)

8805110241 880506
PDR ADOCK 05000413
Q DCD

11
IE01

Duke Power Company

2

MAY 06 1988

bcc w/encl:

K. N. Jabbour, NRR
NRC Resident Inspector
DRS, Technical Assistant
Document Control Desk
State of South Carolina

RII

MB
PBurnett: ser
05/2/88

RII

19
FJape
05/2/88

RII

TP
TPeebles
05/3/88