



Northeast
Utilities System

107 Selden Street, Berlin, CT 06037

Northeast Utilities Service Company
P.O. Box 270
Hartford, CT 06141-0270
(860) 665-5000

SEP 24 1998

Docket Nos. 50-213
50-245
50-336
50-423

B17440

Re: 10CFR26.71(d)

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Haddam Neck Plant
Millstone Nuclear Power Station, Unit Nos. 1, 2, and 3
Correction to Semiannual Fitness-for-Duty Performance Data
for January 1998 through June 1998

- Reference (1): B17420, F. C. Rothen to U.S. Nuclear Regulatory Commission,
"Haddam Neck Plant, Millstone Nuclear Power Station, Unit Nos. 1,
2, and 3 - Semiannual Fitness-for-Duty Performance Data for January
1998 through June 1998," dated August 31, 1998
- Reference (2): B17037, F. C. Rothen to U.S. Nuclear Regulatory Commission,
"Haddam Neck Plant, Millstone Nuclear Power Station, Unit Nos. 1,
2, and 3 - Semiannual Fitness-for Duty Performance Data for July
1997 through December 1997," dated February 25, 1998

The purpose of this letter is to correct errors in above References. Specifically, in Reference (1), Attachment 1, page 3, under "percent confirmed positive rates" the correct number for "Random" should be 0.39 percent, and not 30 percent.


In addition, on the same page under "Management Actions," the actions taken relative to a contractor who tested confirmed positive for a second time should be revised from, "This person will be permanently denied unescorted access at any of Northeast Utilities' nuclear facilities" to "This person will be denied unescorted access at any of Northeast Utilities' nuclear facilities for a period of three years." Please note that this statement should also be revised in Reference (2).

9810020159 980924
PDR ADOCK 05000213
R PDR

The cause of these inaccuracies was determined to be administrative errors. We regret any confusion this information may have caused. If you have any questions regarding this correction or the original submittal, please contact Mr. Mario Robles, Jr. at (860) 447-1791 ext 0279.

Very truly yours,

NORTHEAST UTILITIES SERVICE COMPANY



F. C. Rothen
Vice President - Nuclear Work Services

cc: E. V. Imbro, Director, Millstone ICAVP
H. J. Miller, Region I Administrator
W. M. Dean, Director, Millstone Project Directorate
W. D. Lanning, Director, Millstone Inspections
S. Dembek, NRC Project Manager, Millstone Unit No. 1
D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2
J. W. Andersen, NRC Project Manager, Millstone Unit No. 3
T. L. Fredrichs, NRC Project Manager, Haddam Neck Plant
T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
A. C. Cerne, Senior Resident Inspector, Millstone Unit No. 3
W. J. Raymond, Senior Resident Inspector, Haddam Neck Plant