

RETURN TO ^{PI-137} ~~396-SS~~

70-25



Rockwell International

Rocketdyne Division
Rockwell International Corporation
6633 Canoga Avenue
Canoga Park, California 91303

Telex 698478
ROCKETDYN CNPK



July 26, 1988

In reply refer to 88RC09128

Mr. Leland C. Rouse, Chief
Fuel Cycle Safety Branch
Office of Nuclear Material Safety
and Safeguards
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Revised Radiological Contingency Plan
Special Nuclear Material License No. SNM-21
Docket 70-25

Dear Mr. Rouse:

During a recent routine inspection of activities authorized by NRC License No. SNM-21 by the staff of the Region V Office of the Nuclear Regulatory Commission, it was observed that the existing radiological contingency plan, Document ESG-81-30, as revised March 3, 1982, did not conform to the present operations at Rocketdyne Division of Rockwell International. In discussions with the inspection team, it was agreed that the plan should be revised as necessary to apply accurately to the activities currently authorized by the license.

In discussions with you subsequent to the inspection, it was agreed that it would be appropriate to revise the plan without reducing the response effectiveness of the plan and submit the revised plan to you at NRC Headquarters in accord with License Condition 24 of our License No. SNM-21.

The plan has now been revised and is being reissued as Document RI/RD88-206, "On-Site Radiological Contingency Plan for Rockwell International Operations Licensed Under Special Nuclear Material License No. SNM-21." The new document has been prepared in accord with the standard format for radiological contingency plans and is now completely applicable to the activities currently authorized by License No. SNM-21, as amended October 7, 1987. This revision has not reduced the response effectiveness of the plan and is therefore being submitted in accord with the requirement in 10 CFR 70.32(i). Three copies are enclosed for your information and use.

8809120146 880726
PDR ADOCK 07000025
B PDR

DFD 3
1/1
24565

88RC09128
July 26, 1988
Page 2



Rockwell
International

If you have questions or require additional information, please contact me at (818) 718-3403.

Sincerely yours,

M. E. Remley, Director
Nuclear Safety and Licensing
Rockwell International Division

6436A/bes

Enclosure: Document RI/RD88-206 (3 copies)

cc w/enclosure:

Mr. John B. Martin, Region V Office, NRC

DOCKET NO. 70-25
CONTROL NO. 24565
DATE OF DOC. July 26, 1988
DATE RCVD. June 28, 1988
FCUF PDR
FCAF LPDR
I & E REF.
SAFEGUARDS
FCTC OTHER
DATE 7/29/88 INITIAL SDC