



Illinois Power Company  
Clinton Power Station  
P.O. Box 678  
Clinton, IL 61727  
Tel 217 935-5623  
Fax 217 935-4622

Walter G. MacFarland IV  
Senior Vice President  
and Chief Nuclear Officer

U-603087  
2C.220

September 28, 1998

Docket No. 50-461

10CFR50.73

Document Control Desk  
Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1  
Licensee Event Report No. 1998-031-00

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-031-00: Surveillance Procedures Do Not Adequately Consider Accuracy of Installed Instrumentation in Meeting Technical Specification Requirements for Diesel Generator Loading. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains the following commitments:

- Nuclear Station Engineering will prepare formal calculations for each parameter that required the addition of instrument tolerance to the surveillance procedure.
- A Technical Specification Bases change will be prepared for each evaluated parameter to document whether measurement tolerances have or have not been considered in the Technical Specification value.
- Procedures 9080.01, 9080.02, 9080.13, 9080.14, 9080.21, 9080.22 and 9080.23 will be revised to incorporate the provisions of the license amendment,
- Procedures 9080.01, 9080.02, 9080.13, 9080.14, 9080.21, 9080.22 and 9080.23 will be performed, as required, prior to restart from the current outage.

1/1  
Jerr

Sincerely yours,

Walter G. MacFarland, IV  
Senior Vice President and  
Chief Nuclear Officer

9810020271 980928  
PDR ADOCK 05000461  
S PDR

RAF/krk

Enclosure

cc: NRC Clinton Licensing Project Manager  
NRC Resident Office, V-690  
Acting Regional Administrator, Region III, USNRC  
Illinois Department of Nuclear Safety  
INPO Records Center