Docket No. 50-346

Toledo Edison Company

ATTN: Mr. Joe Williams, Jr.

Vice President

Nuclear

Edison Plaza 300 Madison Avenue Toledo, OH 47652

Gentlemen:

This refers to the routine safety inspection conducted by Messrs P. R. Wohld, C. B. Ramsey, J. M. Ulie, and W. G. Guldemond of this office on February 3-6, 1986, of activities at Davis-Besse Nuclear Power Station authorized by NRC Operating License NPF-3 and to the discussion of our findings with members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by Luis A. Reyes

8603040154 860228 Luis A. Reyes, Chief Operations Branch

Enclosure: Inspection Report No. 50-346/86006(DRS)

See Attached Distribution

Wohld/mab 02/28/86

RIII

RIII

FEB 2 8 1986

Distribution

cc w/enclosure:
L. Storz, Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health