

SEP 02 1988

Official

Docket Nos. 50-325 and 50-324
License Nos. DPR-71 and DPR-62

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Senior Executive Vice President
Power Supply and Engineering
and Construction
P. O. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: NOTICE OF VIOLATION
(NRC INSPECTION REPORT NOS. 50-325/88-24 AND 50-324/88-24)

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by William H. Ruland on July 7 - August 7, 1988. The inspection included a review of activities authorized for your Brunswick facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The inspection findings indicate that certain activities appeared to violate NRC requirements. One violation (325, 324/88-24-01), references to pertinent requirements, and elements to be included in your response are described in the enclosed Notice of Violation. In addition, two other violations (325, 324/88-24-03 and 04) were identified. These violations are described in the enclosed inspection report and are under consideration for escalated enforcement action. Accordingly, no Notice of Violation is being issued at this time, and no response to those particular violations is required. However, please be advised that the number and characterization of violations described herein may change as a result of further NRC review. An Enforcement Conference to discuss these violations has been scheduled for September 8, 1988. You will be advised by separate correspondence of the results of our deliberations on this matter. Also, in one instance, because all of the criteria for categorization of licensee-identified violations were met, the violation is not being cited. The details pertaining to the licensee-identified violation are described in paragraph 14 of the enclosed inspection report.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

8809130163 880902
PDR ADOCK 05000324
Q PIC

1/1
1001

SEP 20 1988

Carolina Power and Light Company 2

The responses directed by this letter and its enclosures are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, please contact us.

Sincerely,

J. Nelson Grace
Regional Administrator

Enclosures:

- 1. Notice of Violation
- 2. NRC Inspection Report


cc w/encls:


P. W. Howe, Vice President
Brunswick Nuclear Project
J. L. Harness, Plant General Manager
State of North Carolina


bcc w/encls:


NRC Resident Inspector
DRS, Technical Assistant
Document Control Desk


RII
RCarroll:tm
09/31/88

RII 
PFredrickson
09/1/88

RII 
DVerrelli
09/1/88

RII 
CHH
09/1/88

RII 
LReyes
09/ /88

RII 
GJenkins
09/2/88

RII
MErnest
~~09/ /88~~