Duquesne Light Company

Beaver Valley Power Station P.O. Box 4 Shippingport, PA 15077-0004

RICHARD D. BRANDT Division Vice President Nuclear Operations and Plant Manager Nuclear Power Division

(412) 393-7622 Fax (412) 393-4905

September 17, 1998 NPD3VPO: 0903

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

NPDES Monthly Report, EPA Permit No. PA0025615

SUBJECT: Beaver Valley Power Station, Unit No. 1 and No. 2 BV-1 Docket No. 50-334, License No. DPR-66 BV-2 Docket No. 50-412, License No. NPF-73

Dear Sir:

Enclosed is a copy of the NPDES Monthly Report as submitted to the Pennsylvania Department of Environmental Protection.

Sincerely,

K.C. Ostrowski for Richard D. Brandt Division Vice President

SLV/trs

cc: D. A. Orndorf J. K Cool S. K. Hobbs Central File

9810050075 980831 PDR ADDCK 05000334 PDR PDR 1/ 1225



Duquesne Light Company

Beaver Valley Power Station P.O. Box 4 Shippingport, PA 15077-0004

RICHARD D. 3RANDT Division Vice Fresident Nuclear Operations and Plant Manager Nuclear Power Division (412) 393-7622 Fax (412) 393-4905

September 17, 1998 NPD3VPO: 0905

Attention: "DMR Clerk"
Department of Environmental Protection
Bureau of Water Quality Management
400 Waterfront Drive
Pittsburgh, PA 15222

NPDES Monthly Report, EPA Permit No. PA0025615

Gentlemen:

NPDES Monthly Report for Duquesne Light Company, Beaver Valley Power Station for August 1998 is submitted for your consideration.

Sincerely,

Richard D. Brandt Division Vice President

K. (Ostrowski for

SLV/trs

cc: D. A. Orndorf J. K. Cool S. K. Hobbs Central File



Duquesne Light Company

Beaver Valley Power Station P.C. Box 4 Shippingport, PA 15077-0004

RICHARD D. BRANDT Division Vice President Nuclear Operations and Plant Manager Nuclear Power Division

(412) 393-7622 Fax (412) 393-4905

September 17, 1998 NPD3VPO: 0904

United States Environmental Protection Agency Region III, Pennsylvania (3WM53) Water Permits Branch Water Management Division 1650 Arch Street Philadelphia, PA 19103-2029

NPDES Monthly Report, EPA Permit No. PA0025615

Dear Sir:

This letter forwards a copy of our NPDES Monthly Report as submitted to the Pennsylvania Department of Environmental Resources, Bureau of Water Quality Management.

Sincerely,

Richard D. Brandt Division Vice President

K.C. Ostrowski for

SLV/trs

Attachment

cc: D. A. Orndorf J. K. Cool S. K. Hobbs Central File



sheets and common 2. Sludge products performance. Redigesters and of from the treatments of the streatment of the streat	ly and submit with each DMR nents as needed for complet for information will be use deport only sludge which had ther solids which have been process. Do not inclust processed at your facility	ty. plant from removed	Permittee: DURUESNE LIGHT COMPAN' Plant: BE AVER VALLEY TOWER STATER NPDES: FA GOZSGIS Municipality: SHIPENGPERT BORGER County: BEAVER					
 In the disposal facility for di of your sludge, dispose of slud disposal site s tonnage on the 	site section, report all sposal. If another plant just provide the name of ge from other plants, inclection and provide their nback of this form. s removed, note on form.	sludge leaving processes and d that plant. If ude their tonna ames and indivi	isposes you ge in the	r sludge that is Pre-incineration Post-incineration	weight =	dry tons dry tons		
HAUL	ED AS LIQUID SLUDGE	CITOR THI ORBATT		HAULED AS DEWATER	ED SLUDGE			
(Gallons) X (% S	(Conversion	Dry Tons	(Tons of Dewatered Slu		ds) X (.01) =	Dry Tons		
13500 2	.0000417	1.13			TOTAL =			
DISPOSAL SITE	INFORMATION: List all site	es, even if not Site 2						
	Site 1 BOROVOH OF MONACA			Site 3	Site	4		
Name:	SEWALE TREATMENTILANT							
Permit No.:	140020125							
ype: (check one) Landfill	143		*					
Agr. Utilization								
Other (specify)								
County:	BEAVER	010	- h					
(SSR-1 3/21/91)		Signature		EMISTRY MANACER	9/22/98 Date	412-393-5 Telephone		

Instructions:

Year: 1498

Instructions: Unit 1. Complete monthly and submit with each DMR. Attach additional Permittee: DUQUESNE LIGHT COMPANY sheets and comments as needed for completeness and clarity. Plant: BEAVER VALLEY 10WEK STATION ... 2. Sludge production information will be used to evaluate plant performance. Report only sludge which has been removed from NPDES: PA 0025615 digesters and other solids which have been permanently removed Municipality: SHIPPINGPORT KURTUEIL from the treatment process. Do not include sludge from other County: BEAVER plants which is processed at your facility. 3. In the disposal site section, report all sludge leaving your For sludge that is incinerated: facility for disposal. If another plant processes and disposes Pre-incineration weight = dry tons Post-incineration weight * dry tons of your sludge, just provide the name of that plant. If you dispose of sludge from other plants, include their tonnage in the disposal site section and provide their names and individual dry tonnage on the back of this form. 4. If no sludge was removed, note on form. SLUDGE PRODUCTION INFORMATION (prior to incineration) HAULED AS LIQUID SLUDGE HAULED AS DEWATERED SLUDGE (Conversion (Tons of X (% Solids) Factor) - Dry Tons (Gallons) Dewatered Sludge) X (% Solids) X (.01) = Dry Tons .0000417 0.46 5500 2 .01 TOTAL TOTAL DISPOSAL SITE INFORMATION: List all sites, even if not used this month Site 2 Site 1 Site 3 Site 4 BOROVON UF MONACA Name: SEVIALE TREATMENTILANT Permit No .: PA 00 20125 Dry Tons Disposed: 0.46 Type: (check one) Landfill Agr. Utilization · Other (specify) County: BEAVER CHEMISTRY MANALER 412-393-5113 (SSR-1 3/21/91)

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLITICANT DISCHARGE ELIMINATION SYSTEM (NPOES) Form Approved. DISCHARGE MONITORING REPORT (DMR) UNITS 182 COOLS, OMB No. 2040/0004 BEAVER VALLEY POWER STATION 12-161 Approvel axpires 05-31-98 P.O. BOY 4 ADDRESS (508R 051 PERMIT NUMBER DISCHARGE NUMBER ATTW: DAVID ORNDORF F - FINAL SHIPPINGPORT DA 15077 MONITORING PERIOD FACILITY DAY YEAR MO DAY YEAR MO LOCATION FROM TO POR NO DISCHARGE NOTE: Read instructions before completing this form. ATTH: DAVID ORNDORS (20-21) (22-23) (24-25) 126-271 (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION 13 Card Only) 14 Card Only FREQUENCY NO. PARAMETER SAMPLE (46-53) 154-611 (38-45) (46-53) (54-61) EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) (69-70) SAMPLE 1 12 8.20 7,74 GRAB MEASUREMENT PERMIT **** 6.0 9.0 VEEKLY GRAD REQUIREMENT EFFLUENT GROSS VALU BIATHOR MAXIRUM SAMPLE MITROGEN. AMMORIA (19 LOSS than LESS thom GRAR 31 MEASUREMENT TOTAL (AS N) detectuble detectable PERMIT REERLIGERA REQUIREMENT EFFICIENT GROSS VALUE NO AVG DATLY NY SAMPLE NA MEASUREMENT MATER PERMIT te de de de WHEN COM 32 REQUIREMENT NO ATC EFFLUENT GROSS VALU DAILY ME DISCH SAMPLE CONTIN 46.8 THRU TREATMENT PLAN MEASUREMENT 50050 1 PERMIT CORTI EFFLUENT GROSS VALU REQUIREMENT HO AYC DAILY MY HGD CHLORINE. SAMPLE 0.00 0.00 GRAB MEASUREMENT RESIDUAL. 255222 200222 * * * * * 50060 1 0 0 PERMIT 0.5 1.25 EFFLUENT GROSS VALUE REQUIREMENT HO AVG IBST BAN 拉索索拉拉车 000000 CHEORINE. SAMPLE 12 COP DE 0.16 0.03 AVAILABLE MEASUREMENT 50064 1 0 0 PERMIT 0.2 0.5 ONTIN E : FLUENT UROSS VALU REQUIREMENT 物业物物 AVERAGE MAKIMUM MG/L RYDRAZINE 200000 Less Ylean SAMPLE Less thanks MEASUREMENT detectable detectoine 医原物性现象 10000 D # 20 20 20 20 PERMIT EBRLIGHT REFELDENT GROSS VALU REQUIREMENT MO AVG DAILY ME MG/L NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED OFFICER OR AUTHORIZED AGENT NUMBER YEAR MO DAY and or maximum imprisonment of between 6 months and 5 years.) COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) ## 6[3] dering August # for 18 days during HYDRAZINE AND ARROHIA MONITORING TO APPLY DURING PERIODS OF NET LAYUP. REPORT THE DAILY MAXIMUM FOR RETZ T-1 WHEN DISCHARGING (24 HR. COMP.): NA MG/L. (THE LIBIT IS 35 MG/L as a DAILY MAX.)

NA: No claimtrol or Betz DT-1 added during August. * One sample taken during the period ** Detection limit is 10000, what Detection limit is EPA Form 3320-1 (08-95) Previous editions may be used.

(REPLACES EPA FORM T-40 WHICH MAY NOT BE USED.)

PAGE

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
 - 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to muricipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum")
 - 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
 - 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
 - 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
 - 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

INTAKE SCREEN BA OMB No. 2040-0004 NAME BEAVER VALLEY POWER STATION (17-19) 12-161 Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) ATTN: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION *** NO DISCHARGE |_ | *** FROM TO ATTN: DAVID ORNDORF NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (28-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION (3 Card Only) 14 Card Only) FREQUENCY NO. PARAMETER SAMPLE (46-53) (54-61) (38-45) (46-53) 154-511 EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS AVERAGE MINIMUM MAXIMUM UNITS (62-63) (64-68) (69-70) FLOW, IN CONDUIT OR SAMPLE (03) 非意志意意 .046 E57. THRU TREATMENT PLAN MEASUREMENT .006 50050 1 0 0 PERMIT REPORT REPORT ******* **** WEDELT ESTIT EFFLUENT GROSS VALU REQUIREMENT NO AVG DAILY MX MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 412,393-5113 Chemistry Manager THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED OFFICER OR AUTHORIZED AGENT NUMBER YEAR MO DAY and or maximum imprisonment of between 6 months and 6 years.) COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

PERMITTEE NAME/ADDRESS (Inchede Faccity Name/Location if Different)

00028/980708-1359

Form Approved. .

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, rathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units see a permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all permits for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are not permit and low measurements obtained during "Monitoring Period." (Note to municipals with preatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/3" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING DEPORT (DMR) Form Approved. « BEAVER VALLEY POWER STATION 003 UNCONTABINAT OMB No. 2040-0004 PR (2-16) ADDRESS P.O. BOX & Approval expires 05-31-98 (SUBR 05) ATTN: DAVID ORNDORP PERMIT NUMBER DISCHARGE NUMBER F - FINAL SRIPPINGPORT PA 15077 EAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION FROM TO COC NO DISCHARGE ! ! COC ATTN: DAVID ORBDORF NGTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) 13 Card Onlyl QUANTI TY OR LOADING (4 Card Only) QUANTITY OR CONCENTRATION PARAMETER FREQUENCY NO. SAMPLE (46-53) 154-611 (38-45) (46-53) 154-611 OF 132-371 EX TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) (69-70) SAMPLE FLOW, IN CONDUIT OR (03)\$\$\$\$\$\$ MEASURSMENT THRU TREATMENT PLAN 50050 1 0 0 PERMIT REPORT REPORT 政策者法法定公 在本意在在在 **** AESTIR REQUIREMENT EFFLUENT GROSS VALU NG AVG DAILY MX MGD BOET SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND 3ASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE BOOSTHILTY OF EINE AND HADDISONMENT. NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE Chemistry Manager THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 393-5113 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 SIGNATURE OF PRINCIPAL EXECUTIVE TYPED OR PRINTED and or maximum, imprisonment of between 6 months and 5 years.) OFFICER OR AUTHORIZED AGENT NUMBER YEAR MO DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor inclinities of it hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurement: obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) " "ified in permit. Retain copy for your records.
- More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. DISCHARGE MONITORING REPORT (DMR) BEAVER VALLEY POWER STATION UNIT ONE COOLS TOMB No. 2040-0004 (17-19) (2-16) Approval expises 05-31,98 ADDRESS P.O. BOX 4 0.04 (SUBR 05) ATTN: DAVID OR DORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY MO DAY YEAR MO DAY LOCATION FROM 中中中 NO DISCHARGE | 1 念章章 TO ATTN: DAVID ORNDORF NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING (3 Card Only) 14 Card Only) QUANTITY OR CONCENTRATION FREQUENCY PARAMETER NO. SAMPLE (46-53) (54-61) (38-45) 146-531 (54-61) EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 152-631 (64-68) (59-70) SAMPLE GRAB MEASUREMENT PERMIT 9.0 REKLIGHAS EFFLUENT GROSS VALU REQUIREMENT 西王其王担以为 西岛美工西经营 FLOW, IN COMBUIT OF SAMPLE 0.100 0.100 THRU TREATMENT PLAN MEASUREMENT 50050 1 0 0 REPORT 意名物品专名 PERMIT 0000 BEASE EFFLUENT GROSS VALU REQUIREMENT MO AVG DAILY MX MGD CHLURINE, TOTAL SAMPLE 0.00 0.00 MEASUREMENT **** PERMIT 1.25 EFFLUENT GROSS VALU REQUIREMENT NO AVG INST HAN HG/L CHLORINE, FREE **化水油水水**点 SAMPLE 0.00 GRAB 0.00 MEASUREMENT 50064 1 0 0 7 10 10 10 10 10 数数数数数数 2000 PERMIT 0.5 EFFLUENT GROSS VALU REQUIREMENT MAXIBUM SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FRMILIAR WITH THE INFORMATION SUBMIT (ED HEREIN; AND BASED ON INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 7319. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED NUMBER OFFICER OR AUTHORIZED AGENT YEAR MO DAY and or maximum imprisonment of between 6 months and 6 years.) COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) There was flow only once during August. Measured not obtained is an est mate. FELLIE

00032/980708-1359

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to municipals with secondary treatment requirement. Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0",
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

AUX . INTAKE SCREE OMB No. 2040-0004 12-161 Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) PERMIT NUMBER DISCHARGE NUMBER ATTN: DAVID ORNDORP F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION FROM *** NO DISCHARGE 1 TC NOTE: Read instructions before completing this form. ATTN: DAVID ORNDORF (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION (3 Card Only) (4 Card Only) FREQUENCY PARAMETER NO. SAMPLE (46-53) (54-61) (38-45) (46-53) 154-611 EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-631 164-681 (69-70) FLOW, IN CONDUIT OR SAMPLE 水中の中の中の EST. .002 -016 THRU TREATMENT PLAN MEASUREMENT PERMIT REPORT **** 50050 1 0 0 在本位立立本 proppe dece REPORT HEEKLYESTIE REQUIREMENT EFFLUENT GROSS VALU NO AYG DAILY MI MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 09 THE POSSIBILITY OF SIME AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penatues under these statutes may include fines up to \$10,000 TYPED OR PRINTED NUMBER YEAR and or maximum imprisonment of between 6 months and 6 years.) OFFICER OR AUTHORIZED AGENT MO DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

PERMITTEE NAME/ADDRESS (Include Facility Name/Location of Different)

BEAVER VALLEY POWER STATION

Form Approved.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM 223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "to discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location of Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. * DISCHARGE MONITORING REPORT (DMR) AUX. INTAKE SYST OMB No. 2040-0004 BEAVER VALLEY POWER STATION 12-161 Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) ATTN: DAVID DRNDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR | MO | DAY YEAR MO DAY LOCATION PPR HO DISCHARGE FROM TO ATTN: DAVID ORNBORF NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION 13 Card C 1/VI 14 Card Only) NO. FREQUENCY SAMPLE PARAMETER (46-53) 154-611 (38-45) (46-53) (54-61) EX 132-371 TYPE ANALYSIS AVERAGE MAXIMUM UNITS AVERAGE UNITS MINIMUM MAXIMUM 162-631 (64-68) (69-70) **** SAMPLE MEASUREMENT 00400 1 0 0 **企业企业企业** 中华中华中 1 PERMIT 6.0 9.0 FERLYGRAB REQUIREMENT EFFLOENT GROSS VALUE MINIMUM MAXIMUM PLOW. IN COMBUIT OR SAMPLE THRU TREATHENT PLAN MEASUREMENT 50050 1 0 0 ***** おかなおなな からさか WEEKLYESTIE PERMIT EFFLUENT GROSS VALU REQUIREMENT NO AVG DAILY ME 草草类香草 存在存存效率 你你你敢你心 CHLORINE, TOTAL SAMPLE (19 RESIDUAL MEASUREMENT 50060 1 0 0 NEW TRANS E E STEEL ST 1000 游戏旅游旅游这 1.25 PERMIT REEALMGRAD REQUIREMENT EFFLUENT GROSS VALU NO AVG IBST HAN RESPUES TO THE CHLORINE, FREE 非方式之故意必 草原合意意 SAMPLE MEASUREMENT AVAILABLE V44020 以及 20 20 20 20 CM 本垃圾垃圾 50064 1 0 0 蒙 等 禁 思 等 等 WEERL GRAS PERMIT 0.5 EFFLUERT GROSS VALU REQUIREMENT AFERAGE MAXIMUE SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

MONITORING FOR FLOW, FREE AVAILABLE CHLORINE, AND TOTAL RESIDUAL CHLORINE ARE REQUIRED ONLY DURING THOSE PERIODS OF DISCHARGE FROM THE ALTERWATE FLOW PATH OF THE REACTOR PLANT RIVER WATER SYSTEM.

SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 AND 33

U.S.C. § 1319. (Pensities under these statutes may include fines up to \$10,000

and or maximum imprisonment of between 6 months and 5 years.)

Chemistry Manager

TYPED OR PRINTED

SIGNATURE OF PRINCIPAL EXECUTIVE

OFFICER OR AUTHORIZED AGENT

NUMBER

00038/980708-1359

YEAR MO

DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Ender "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont." for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) Form Approved. . DISCHARGE MONITORING REPORT (DMR) NAME UNIT 1 COOLING TOMB No. 2040-0004 BEAVER VALLEY POWER STATION (2-15) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) PERMIT NUMBER DISCHARGE NUMBER F - FINAL ATTN: DAVID ORBDORF SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION *** NO DISCHARGE FROM TO NOTE: Read instructions before completing this form. ATTN: DAVID ORROORF (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) (3 Card Only) QUANTITY OR LOADING 14 Card Only) QUANTITY OR CONCENTRATION FREQUENCY NO. PARAMETER SAMPLE (46-53) (54-61) (38-45) (46-53) (54-61) OF EX TYPE (32-37) ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) 169-701 SAMPLE 7.90 7.65 MEASUREMENT 1 0 0 PERMIT 5.0 9.0 EFFLUENT GROSS VALU REQUIREMENT SINIBUS HAYIMUH MONT SAMPLE SOLIDS. TOTAL MEASUREMENT Professional Contracts bana 100 PERMIT REQUIREMENT BO AVG DAILY ME EFFLUENT GROSS VALU OIL AND GREASE SAMPLE < 5 <5 MEASUREMENT FREON EXTR-GRAV PERMIT GRAB REQUIREMENT EFFLUENT GROSS VALU HO AVG DAILY MI INST BAY MONT FLOW, IN CONDUIT SAMPLE (03) .001 <.001 MEASUREMENT 50050 1 0 章章章章章 中中中心 PERMIT REQUIREMENT EFFLUENT GROSS VALU NO AYG DAILY MX MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER

Chemistry Manager

TYPED OR PRINTED

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 and or maximum imprisonment of between 6 months and 5 years.)

SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT

00041/980708-1359

TELEPHONE DATE 393-5113 AREA NUMBER YEAR MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

REQUIREMENT

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency. 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.

 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7 Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring. "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name Location if Different) NAME BEAVER VALLEY POWER STATION

ADDRESS P.O. BOX 4

ATTN; DAVID ORRDORF

SHIPPINGPORT

PA 15077

FACILITY LOCATION

ATTM: DAVID ORNOORS

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM INPOES! DISCHARGE MONITORING REPORT (DMR) (2-16)

MONITORING PERIOD

TO

PERMIT NUMBER

YEAR MO DAY

FROM

DISCHARGE NUMBER

YEAR MO DAY

UNIT 2 COOLING WOMB No. 2040-0004 (SUBR 05) F - PINAL

MAJOR

Form Approved. . Approval expires 05-31-88

** NO DISCHARGE

NOTE: Read instructions before completing this form

PARAMETER (32-37)	1	(3 Card Only) QUANTITY OR LOADING			(4 Card Only) QUA (38-45)	NTRATION (54-61)	"		FREQUENCY	SAMPLE	
	X	AVERAGE	MAXIMUM	UNITS	MINIMUM	(46-53) AVERAGE	MAXIMUM	UNITS	EX (62-63)	ANALYSIS	TYPE (69-70)
PH	SAMPLE MEASUREM		*****		7.86	****	8,20	(12	0	117	GRAB
00460 1 0 0 EFFLUENT GROSS VALU	PERMIT		*****	0000	6.0 HININUM	京京中央市	9.0 MAKINDE	50		WEEEL	GRAS
LASTROL CT-1, TOTA WATER	SAMPLE		*****		专办专业水市	NA -	>	(19	N/9		>
04251 1 0 0 EFFLUENT GROSS VALU	PERMIT		000000	****	*****	NO AVG	O INST KA	M MG/L		NHEM DISC	COMP 2
LOW, IN CONDUIT OF	1	the same of	5.76	(03)	****	· · · · · · · · · · · · · · · · · · ·	00000		0	11/7	MEASEL
50050 1 0 0 EFFLUENT GROSS VALU	PERMIT		REPORT DAILY MX	EGD	专业企业企业	李李泰泰李安	\$\$00\$0	\$\$\$\$		WEEKL	NEASI
RESIDUAL	SAMPLE MEASUREM		244444		****	0.00	0.00	(-19)	0	1/7	GRAB
50060 1 0 0 SFFLUERT GROSS VALU	PERMIT		000000	****	\$25000	NO AVE	1.25 IMST MA	X MG/L		WEEKL	BGRAS
CHLORINE, FREE	SAMPLE MEASUREM		*****		000000	0.00	0.00	(19)	0	1/7	GRAB
30064 1 0 0 EFFLUENT GROSS VALU	PERMIT		******	0000	\$10.00 to 10.00	O.Z AVERAGE	U.S SAXINUS	MG/L		WEERL	GHAB
	S.AMPLE MEASUREM										
	PERMIT										
	SAMPLE										
	PERMIT							1			
AM FAM		CERTIFY UNDER PENALTY OF	RMATION SUBMITTED H	EREIN; AND B	ASED ON	100	OF	TELEPHO	VE S	Di	ATE
David Orndorf OBTA		MY INQUIRY OF THOSE IN BETAINING THE INFORMATION RUE, ACCURATE AND CON IGNIFICANT PENALTIES FOR	N, I BELIEVE THE SUBMI MPLETE. I AM AWA SUBMITTING FALSE INF	TTED INFORM. RE THAT THE	ATION IS ERE ARE CLUDING	Stand	100	12 493-5	113	98 0	9 17
U.S.C		THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. § 1001 U.S.C. § 1319. (Peralties under these statutes may include fines up to and or maximum imprisonment of between 6 months and 5 years.)						REA NUMBE	-	-	NO DAY

REPORT THE DAILY MAXIMUM FOR BETZ DT-1 WHEN DISCHARGING (24 HR. COMP.) : NA MG/L. (THE LIBIT IS 35 M G/L AS A DAILY MAX.) NA- Not applicable. No clembrol or betz DT-1 added during August.

PAGE

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during mouitoring period, enter "No Discharge" across form in place of data entry
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

DISCHARGE MONITORING REPORT (DMR) NAME DIESEL GER & TOR OMB No. 2040-0004 BEAVER VALLEY POWER Sa TION (2-16) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SORR 05) ATTN: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT PA 15077 RAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION *** NO DISCHARGE ! FROM TO NOTE: Read instructions before completing this form. ATTH: DAVID OHNDORF (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING (4 Card Only) QUANTITY OR CONCENTRATION 13 Card Onlyl FREQUENCY NO. PARAMETER SAMPLE (46-53) 154-611 (38-45) 146-531 154-611 EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) 169-701 SAMPLE ***** FLOW, IN COMDUIT OR ,002 .002 EST. THRU TREATMENT PLAN MEASUREMENT PERMIT REPORT 办事者改革家 李章帝正立本 医医医医孔囊医虫虫亚属 REQUIREMENT EFFLUENT GROSS VALU MO AYG DAILY BA MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT I CESTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FACILLIAR WITH THE INFORMATION SUBMITTED HEREIN: AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 98 412 393-5113 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED NUMBER and or maximum imprisonment of between 6 months and 5 years.) OFFICER OR AUTHORIZED AGENT YEAR MO DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if L.

00047/980708-1359

Form Approved.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, ¹⁰ Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Wg ugton, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. DISCHARGE MONITORING REPORT (DMR) BEAVER VALLEY POWER STATION OMB No. 2040-0004 SLOWDOWN FROM TH (2-16) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) ATTN: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL PA 15077 SHIPPINGPORT MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION * P NO DISCHARGE | | PP+ FROM TO ATTH: DAVID ORNDORP NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION (3 Card Only) (4 Card Only) NO. FREQUENCY PARAMETER SAMPLE (46-53) (54-61) (38-45) 146-531 (54-61) EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) 169-701 市立立立立立: SAMPLE 1 12 1.68 MEASUREMENT 00400 1 0 0 PERMIT 2000 9.0 信息基础 REQUIREMENT EFFLUENT GROSS VALU MINIMUM MINIER MORT FLOW. IN CONDUIT OR SAMPLE (03) .010 THRU TREATMENT PLAN MEASUREMENT .010 50050 1 0 0 PERMIT THEE! ESTIN REQUIREMENT EYPLUENT GROSS VALU SO AVG DAILY MX MGD 哲心证明 SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SANIPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING Chemistry Manager THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1318. (Pensities under these statutes may include fines up to \$10,000 AREA NUMBER TYPED OR PRINTED OFFICER OR AUTHORIZED AGENT YEAR MO DAY and or maximum imprisonment of between 6 months and 5 years.)

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

00050/980708-1359

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Fl equency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR) PERMITTEE NAME/ADDRESS (Include Facility Name/Location (f Different) BEAVER VALLEY POWER STATION OUTFALL 013 (2-16) ADDRESS P.O. BOX 4 (SUBR 05) DISCHARGE NUMBER ATTN: DAVID OREDORF PERMIT NUMBER F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY

Form Approved. . OMB No. 2040-0004 Approval expires 05-31#98

YEAR MO DAY YEAR MO DAY LOCATION FROM TO

occ NO DISCHARGE

ATTN: DAVID ORNDORF			(20-21) (22-23) (24-25) (25-27) (28-29) (30-31) NOTE: Read instructions before completing this for									
PARAMETER (32-37)		(3 Card Only) QUANTITY OR LOADING (46-53) (54-61)			(4 Card Only) QUANTITY OR CONCENTRATION (54-61)			, ,		FREQUENCY	DAMILLE	
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX (62-63)	ANALYSIS (64-68)	TYPE (69-70)	
PH	SAMPLE MEASUREMENT	****	****		7.67	改杂杂杂杂杂	7.86	(12)	0	1/7	GRAE	
00400 1 0 0 EFFLUENT GROSS VALU	PERMIT REQUIREMENT	*****	*****	0000	6.0 MINIMUM	****	9.0 BAXISUE	50		VEERL)	GRAS	
PLOW, IN COSDUIT OF TARU TREATMENT PLAN SOOSO 1 0 0 EPPLUENT GROSS VALU CHLORINE, TOTAL RESIDUAL	SAMPLE MEASUREMENT	.009	. 015	(03)	****	****	****	-	0	1/7.	EST.	
	PERMIT REQUIREMENT	REPORT NO AVS	BEPORT DAILY BE	agp	000000	****	存在存在存在	0000		RESKL	ESTIN	
	SAMPLE MEASUREMENT	\$4440	****		, 000000	0.38	1.30	(19)	0	2/31	CALCTO	
50060 1 0 0 EFFLUENT GROSS VALU	PERMIT REQUIREMENT	泰泰安泰泰	*****	0000	*****	REPORT EO AVG	REPORT INST MA	X MG/L			CALCI	
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT											
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT											
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT											
	SAMPLE MEASUREMENT											
	PERMIT REQUIREMENT											
		FY UNDER PENALTY OF I							IE	DA	ATE	
Dovid Orndorf OBTA Chemistry Manager TRUE, SIGNII		IQUIRY OF THOSE IN NING THE INFORMATION ACCURATE AND CON ICANT PENALTIES FOR ISSIBILITY OF FINE AND	DIVIDUALS IMMEDIATE , I BELIEVE THE SUBMI HPLETE, I AM AWA SUBMITTING FALSE INF IMPRISONMENT, SEE 18	LY RESPONSI ITTED INFORM. RE THAT THI ORMATION, IN I U.S.C. § 1001	RLE FOR ARTION IS CITED AND 33 412 392 113 5				98	09 17		
		§ 1319. (Penalties unde maximum imprisonment of (Reference ell attra	between 6 months and 6			ICER OR AUTHORIZE	D AGENT CO	DE NUMBE	R	YEAR N	O DAY	

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

THERE SHALL BE NO DISCHARGE OF FLOATING SOLIDS OR VISIBLE FOAM IN OTHER THAN TRACE AMOUNTS.

00053/980708-1359

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. * DISCHARGE MONITORING REPORT (DMR) OMB No. 2040-0004 SEAVER VALLEY POWER STATION 101 CHERICAL WAS 12-161 Approval expires 05-31-98 ADDRESS P.D. BOX 4 (SUBR 05) PERMIT NUMBER DISCHARGE NUMBER ATTH: DAVID ORNDORF F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION ### NO DISCHARGE | FROM NOTE: Read instructions before completing this form. ATTN: DAVID ORNDORF (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION (3 Card Only) (4 Card Only) FREQUENCY NO. PARAMETER SAMPLE (46-53) 154-611 (38-45) (46-53) (54-61) EX 132-371 TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-631 (64-68) 169-701 SAMPLE GRAB 7.04 MEASUREMENT 00400 1 0 0 PERMIT 2000 9.0 FEEKLY GEAS REQUIREMENT EFFLUENT GROSS VALU MINIMUM BAXINUS SAMPLE SOLIDS, TOTAL MEASUREMENT COMP *********** ***** PERMIT REQUIREMENT EFFLUENT GROSS VALUE A AVG DAILY BE MPLE ME REMENT PERMIT the star the life REQUIREMENT EFFLUENT GROSS VALU MO AVG MG/L DAILY MN SAMPLE 市市市市市中: WITHOGEN, AMMONIA 14.3 MEASUREMENT TOTAL (AS N) PERMIT 非常专作业业 REPORT REQUIREMENT RFFLUENT GROSS VALU DAILY MM SAMPLE (03) CONTIA THRU TREATMENT PLAN MEASUREMENT PERMIT \$\$\$\$\$\$\$ CONTI REQUIREMENT EFFLUENT GROSS VALU HO AVE DATLY NE Less Than SAMPLE MEASUREMENT than detectable detectable 动物物物物 81313 1 PERMIT WEEKL #GRAB SFFLUENT GROSS VALU REQUIREMENT BO AVG DAILY SX 8G/L SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON

TYPED OR PRINTED

MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 and or maximum imprisonment of between 6 months and 5 years.)

SIGNATURE OF PRINCIPAL EXECUTIVE

OFFICER OR AUTHORIZED AGENT

00057/980708-1359

412,393-5113 NUMBER YEAR MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) ## Datetion limit is 10 ppb. # are composited but discharge Damples HYDRAZINE AND AMMONIA MONITORING TO APPLY DURING PERIODS OF WET LAYUF. + mes are much less than 2 hours, * Samples taken at least once per week. The plant was in wet layup during the tirst week of August.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mril signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. * DISCHARGE MONITORING REPORT (DMR) BEAVER VALLEY POWER STATION 102 INTAKE SCREE OMB No. 2040-0004 12-16) (17-19) ADDRESS P.O. BOX 4 Approval expires 05-31-98 (50BR 05) ATTN: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT PA 15077 KAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION FROM *** NO DISCHARGE ! TO ATTN: DAVID ORNDORF NOTE: Posd instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION (3 Card Only) 14 Card Only) NO. FREQUENCY PARAMETER SAMPLE (46-53) (54-61) (38-45) (48-53) (54-61) (32-37) EX TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-53) (64-68) (69-70) SAMPLE 7.89 MEASUREMENT PERMIT A REST OF THE PARTY. 你你你你你 食力力力 0.0 AGRAB EFFLUENT GROSS VALU REQUIREMENT MINIMUN MARINEE 器の科学 SOLIDS, TOTAL SAMPLE 24 2/31/6RAB MEASUREMENT 00500 1 0 0 PERMIT *** EFFLORNT GROSS VALU REQUIREMENT MO AVG DAILY SN SONT **建筑水均均均** 於放於於於非於 OIL AND GREASE SAMPLE FREON EXTR-GRAY MET MEASUREMENT ***** 拉拉斯斯斯拉 电次次次 PERMIT WICE/GRAE EFFLURNT GROSS VALU REQUIREMENT HO AVG DAILY MN MONT 京京京京京京 FLOW, IN CUNDUIT OR **建设设定设** SAMPLE < ,001 < .00 THRU TREATMENT PLAN MEASUREMENT 50050 1 0 0 REPORT \$5 \$5 \$5 \$5 \$5 \$5 PERMIT 泰黎落臺灣草 经水本金 EFFLUENT GROSS VALU REQUIREMENT SO AVG DAILY MX MGD MOST SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 393-5113 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

and or maximum imprisorment of between 6 months and 5 years.)

TYPED OR PRINTED

NUMBER

YEAR

MO

OF

DAY

OFFICER OR AUTHORIZED AGENT

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location of Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM INPOEST Form Approved. DISCHARGE MONITORING REPORT (DMR) OMB No. 2040-0004 BEAVER VALLEY POURS STATION SLUDGE SETTLING 12-16; Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) PERMIT NUMBER DISCHARGE NUMBER ATTN: DAVID ORNDORF P - FIHAL PA 15077 MAJOR MONITORING PERIOD FACILITY MO DAY YEAR MU DAY YEAR LOCATION FROM *** NO DISCHARGE TO NOTE: Read instructions before completing this form. ATTN: DAVID ORNDORF (20-21) (22-23) (24-25) 126-27) (28-29) (30-31) QUANTITY OR CONCENTRATION QUANTITY OR LOADING 13 Card Only) 14 Card Only) FREQUENCY NO. SAMPLE PARAMETER (46-53) 154-61) (38-45) (46-53) (54-61) OF EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (54-68) (69-70) SAMPLE 京章章章章: (12 7.78 MEASUREMENT PERMIT **企业在仓库**在 the six also the six at 00400 1 0 0 立章章章章章 9.0 6.0 AGREB. REQUIREMENT EFFLUENT GROSS VALO MIMIMUM MAXIBUS BONT SAMPLE 态意由立态自 SOLIDS. TOTAL (19) MEASUREMENT COMP 00530 1 **建筑物** 100 PERMIT REQUIREMENT EFFLUENT GROSS VALU DAILY MY BORT BO AVG SAMPLE FLOW. IN COMBUIT OF (03) 2/31 EST. .006 .002 THRU TREATMENT PLAN MEASUREMENT PERMIT REPORT 50050 1 0 0 THICE/ESTIN EFFLUENT GROSS VALUE REQUIREMENT ec ave DAILY MX MGD RORT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING Chemistry Manager 412, 393-5113 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1318. (Penalties under these statutes may include fines up to \$10,000 TYPED OR PRINTED NUMBER YEAR and or maximum imprisonment of between 6 months and 6 years.) OFFICER OR AUTHORIZED AGENT MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

00063/980708-1359

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1: If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

UNIT 2 SERVICE W OMB No. 2040-0904: N (2-16) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) ATTN: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FIWAL SHIPPINGPORT PA 15077 ROLLE MONITORING PERIOD FACHITY YEAR MO DAY YEAR MO DAY LOCATION *** NO DISCHARGE FROM TO ATTM: DAVID DRNDORF NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) (3 Card Only) QUANTITY OR LOADING (4 Card Only) QUANTITY OR CONCENTRATION NO. FREQUENCY SAMPLE PARAIMETER (46-53) 154-611 (38-45) (46-53) (54-61) EX (32-37) TYPE ANALYSIS UNITS AVERAGE MAXIMUM MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) 169-701 FLOW, IN CONDUIT OR SAMPLE (03) THRU TREATMENT PLAN MEASUREMENT 50050 1 0 0 政治市家政治 拉尔克尔 PERMIT REPORT RESELLESTIN EPPLUENT GROSS VALU REQUIREMENT HO AVG DAILY MX MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE Chemistry Manager SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING +12+393-5113 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1318. (Penelties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED NUMBER YEAR NiO and or maximum imprisonment of between 6 months and 6 years.) OFFICER OR AUTHORIZED AGENT DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

PERMITTEE NAME/ADDRESS (Enclude Facility Name/Location (f Different)

BEAVER VALLEY PORER STATION

Form Approved. *

00066/980708-1359

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained curing "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or munimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approveds DISCHARGE MONITORING REPORT (DMR) 111 DIESEL GENER OMB No. 2040-0004 BEAVER VALLEY POWER STATION (2-16) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBE 05) ATIA: DAVID ORMDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT Pa 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION FROM *** NO DISCHARGE TO NOTE: Read instructions before completing this form. ATTN: DAVID ORNDORF 120-21 122-231 (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING (3 Card Only) 14 Card Only) QUANTITY OR CONCENTRATION FREQUENCY PARAMETER NO. SAMPLE (46-53) 154-611 (38-45) (46-53) (54-61) EX (32 37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) (69-70) SAMPLE MEASUREMENT 00400 1 0 0 PERMIT 9.0 6.0 REEKLYGRAS REQUIREMENT EFFLUENT GROSS VALU MINIMUM BESISSE SAMPLE SOLIDS, TOTAL MEASUREMENT SUSPENDED 00530 1 0 0 PERMIT 建设金金金 100 WEERLIGRAR REQUIREMENT EFFLUENT GROSS VALU MO AVG DAILY MX SAMPLE OIL AND GREASE FREOR EXTR-GRAV MET MEASUREMENT 00556 1 0 0 PERMIT 赤安全在安东 15 20 WREELIGRAD REQUIREMENT EFFLUENT GROSS VALU HO AVG DAILY SX MG/L INST MAN SAMPLE PLOW. IN COMDUIT OF THRU TREATMENT PLAN MEASUREMENT PERMIT REPORT **建设企业企业** REEKLIESTIN EFILUENT GROSS VALU REQUIREMENT BO AVG DAILY MY MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICE: TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN: AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 112 393-5113 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED NUMBER YEAR and or maximum imprisonment of between 6 months and 5 years.) OFFICER OR AUTHORIZED AGENT MO DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, atc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Mome/Location (f Different) NATIONAL POLLUTANT DISCHARGE ELIN JATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR) Form Approved. » NAME BEAVER VALLEY POWER STATION UNIT 2 SEWAGE THOMB No. 2040-0004 (2-16) (17-19) ADDRESS P.O. BOX 4 Approval expires 05-37-98 (SUBR 05) ATTM: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION FROM DAS NO DISCHARGE TO ATTM: DAVID ORNDORF NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) 126-271 (28-29) (30-31) QUANTITY OR LOADING (3 Card Only) QUANTITY OR CONCENTRATION (4 Card Only) PARAMETER FREQUENCY NO. SAMPLE 146-531 154-611 (38-45) (46-53) 154-611 132-371 OF EX TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-63 (64-68) (69-70) BER VEC SAMPLE 非非法或非正的 办办办办办公司 MEASUREMENT GRAB 00400 1 0 0 PERMIT 章 的 点 表 表 是 是 **克森森森森森森** 00000 6.0 **市市市市市市** 9.0 TWICE GRAS EFFLUENT GROSS VALUEREQUIREMENT 中华中众 BINIBUR MARTMON NONT SOLIDS, TOTAL 京京京市市市市 SAMPLE 冷冻企会在北 珍珠珠珠在最 8 HR SUSPENDED MEASUREMENT COMP 00530 1 0 0 PERMIT 草草的水质纹纹 拉拉拉拉拉拉拉 becke 海南港市市市 60 CONP-EFFLUERT GROSS VALU REQUIREMENT 中华中华 NO AVG DAILY MM MC/L 西门屋里 FLOW, IN COMPUTE O SAMPLE 你你你你你们 非常原始在自 (03) 0,005 MEASED THRU TREATMENT PLAN MEASUREMENT 0.012 50050 1 0 0 0.043 REPORT PERMIT 中毒毒毒毒毒 经企业股本金 中中中中 WEEKLIMEASA EFFLUENT GROSS VALU REQUIREMENT NO AVE DAILY MX MGD 市市政府市 CHLORINE, TOTAL SAMPLE 享取政立政政 (19 GRAB RESIDUAL MEASUREMENT 0.55 1.58 50060 1 0 0 **建筑设施设设 没是你要要说** tiana. 计可靠的表示 PERMIT REPORT REPORT 120 (0.5 GRAS SFFLUENT GROSS VALUEREQUIREMENT 政治库库 HO AVG INST MAN MG/L HORT COLIFORN, FECAL 以政政政政院院 草原原原原本原 SAMPLE 章章章章章章 非常非常於 GRAR GENERAL MEASUREMENT 74055 1 0 0 THE REAL PROPERTY. **建设设设设施** tract to PERMIT 対抗ななははは \$45544E 8/ 200 TRICE SHAB EFFLUENT GROSS VALU REQUIREMENT SO GEORE 1004 MONT BUD, CARBURACEOUS THE PERSON NAMED IN SAMPLE 拉於 拉 次 经 拉 00000 (19 SHIR 05 DAY, 20C MEASUREMENT romp 80082 1 0 0 200000 PERMIT 常也也是在在 nean 京市市市市市市 THICE COMP-EFFLUENT GROSS VALU REQUIREMENT **拉拉拉拉** NO AVG DATLY MX MG/L MONT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THE E INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFOR' ATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING David Orndorf 393-5113 98 09 17 Chemistry Manager THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 TYPED OR PRINTED OFFICER OR AUTHORIZED AGENT and or maximum imprisonment of between 6 months and 6 years.) NUMBER YEAR MO DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

EPA Form 3320-1 (08-95) Previous editions may be used.

one per week.

* tortormed at least

(REPLACES EPA FORM T-40 WHICH MAY NOT BE USED.)

00072/980708-1359

PAGE

OF

2.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 461 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Propal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved: PERMITTEE NAME/ADDRESS (Include Facility Name/Location of Different) DISCHARGE MONITORING REPORT (DMR) 201 SOFTENER REG OMB No. 2040-0004 NAME BEAVER VALLEY POWER STATION 12-161 Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) PERMIT NUMBER DISCHARGE NUMBER F - FINAL ATTH: DAVID ORNDORF TEOGRAGACINE PA 150." MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION *** NO DISCHARGE FROM TO NOTE: Read instructions before completing this form. ATTS: DAVID ORNOORF 126-27) (28-29) (30-31) 120-211 122-231 124-251 QUANTITY OR CONCENTRATION (3 Card Only) QUANTITY OR LOADING 14 Card Onlyi NO. FREQUENCY SAMPLE PARAMETER (46-53) (54-61) (38-45) (46-53) (54-61) EX TYPE 132-371 ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) (69-70) SAMPLE 1 12 MEASUREMENT PERMIT 中非中华地中 00400 1 0 0 SAED VEDIEL 0.0 9.0 REQUIREMENT EFFLUENT GROSS VALU BIRTHUN MARTHUM SAMPLE (19) SOLIDS, TOTAL MEASUREMENT 施索费施费费 自立立立 "WICE GRAB 00539 1 0 0 PERMIT EFFLUENT GROSS VALU REQUIREMENT NO AVC DAILY 52 FORT SAMPLE MEASUREMENT FREDE EXTR-GRAV MET printing books PERMIT TWICE GRAS REQUIREMENT EFFLUERT GROSS VALU SO AVG DAILY MN BONT FLOW, IN CONDUIT OF SAMPLE (03) MEASUREMENT THRU TREATMENT PLAN 50050 1 0 0 PERMIT WICE/ESTIB REQUIREMENT EFFLUENT GROSS VALU MO AYG DAILY CX MORT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

Chemistry Manager

TYPED OR PRINTED

OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING

THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33

U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000

and or maximum imprisonment of between 6 months and 5 years.)

393-5113

NUMBER

AREA

SIGNATURE OF PRINCIPAL EXECUTIVE

OFFICER OR AUTHORIZED AGENT

YEAR! MO

DAY

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0",
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Fermit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location of Different) N.\ME BEAVER VALLEY POWER STATION ADDRESS P.O. BOX 4 ATTN: DAVID ORNDORF SHIPPINCPORT PA 15077

FACILITY

LOCATION

DISCHARGE MONITORING REPORT (DMR) (2-16) (17-19) (2-16) PERMIT NUMBER DISCHARGE NUMBER

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

MAIN SEWAGE THT (SUBR 05) F - FINAL

Form Approved. * OMB No. 2040-0004 Approval expires 05-31-98

MAJOR

*** NO DISCHARGE

NOTE: Read instructions before completing this form.

MONITORING PERIOD YEAR MO DAY YEAR MO DAY FROM TO ATTN: DAVID ORRBORF (20.21) (22.22) (24.25) /26.271 /28.201 /20.311

PARAMETER (32-37)		(3 Cerd Only) QUANTITY OR LOADING (54-51)			(4 Card Only) QUI	NTRATION (54-61)			FREQUENCY OF	SAMPLE	
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX (62-63)	ANALYSIS (64-68)	TYPE (69-70)
PH	SAMPLE MEASUREMEN	TV STATE OF THE ST	*****		7.70	农场市市市 市	7,88	(12)	0	2/31	GRAE
00400 1 0 0 SFFLUENT GROSS VALU	PERMIT REQUIREMEN	\$ \$ \$ \$ \$ \$ \$ \$	最初的最后在	2000	6.0 MINIBUS	乔泰泰泰泰泰	9.0 MAXISUM	SU		TWICE,	GRAB
SOLIDS, TOTAL SOSPENDED	SAMPLE MEASUREMEN	数数数数数数 VT	*****		****	18	19	(19)	0	2/31	COMP
00530 1 0 0 EFFLUENT GROSS VALU	PERMIT REQUIREMEN	п	泰泰泰泰泰泰	0000	949594	NO AVG	DAILY MI	MG/L			CORP
FLOW, IN CONDUIT OR THRU TREATMENT PLAN		NT .004	.006	(03)	*****	****	李小心中中。		0	1	MEASR
50050 1 0 0 EFFLUENT GROSS VALU	PERMIT REQUIREMEN	T NO AVS	REPORT DAILY MX	agp	****	****	\$40,000	*****		WEERLY	BEAS
CHLORINE, TOTAL RESIDUAL	SAMPLE MEASUREMEN	VT SSSSSS	农安安安市		****	0.31	0.57	(19)	0	11/31	GRAI
50060 1 0 0 EFFLOENT GROSS VALU	PERMIT	π	李安安安安安	0000	****	REPORT MO AVS	REPORT INST SA.	MG/L		TWICE/	GRAB
COLIFORM, FECAL GENERAL	SAMPLE MEASUREMEN	\$ \$ \$ \$ \$ \$ \$	教章称亦亦敬		****	and the second	400000	(13)	0	2/31	GRAB
74055 1 0 0 EFFLUERT GROSS VALU	PERMIT REQUIREMEN	中 章章章章章 (T	*****	2000	240000	MO GEOMN	****	#/ 100mm		TWICE/	GRAB
BOD, CARBONACEOUS 05 DAY, 20C	SAMPLE MEASUREMEN	VT STATES	****		200000	2.1	2.1	(19)	0	2/31	BHR. COMP
80082 1 0 0 EFFLUENT GROSS VALU	PERMIT REQUIREMEN	т	\$\$\$\$\$\$\$	\$\$ \$\$ \$	市业农业会会	25 NO AVS	50 DAILY MY	MG/L		TWICE	Secretary Control of the Control of
	SAMPLE MEASUREMEN	NT									
	PERMIT REQUIREMEN	п									
NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY AM FAMILIAR WITH THE II MY INQUIRY OF THOSE			RMATION SUBMITTED H	HEREIN; AND B	ASED ON	NO 1) DE	TELEPHON	IE	DA	TE
David Orndorf Chemistry Manager	OBT TRU SIGI THE	TAINING THE INFORMATION JE, ACCURATE AND COM NIFICANT PENALTIES FOR S POSSIBILITY OF FINE AND II .C. \$ 1319. (Penalties under	, I BELIEVE THE SUBMI PLETE. I AM AWA SUBMITTING FALSE INF MPRISONMENT. SEE 18	RE THAT THE ORMATION, IN B U.S.C. \$ 100	ATION IS ERE ARE ICLUDING I AND 33	TURE OF PRINCIPAL	EVERTITALE	2 393-5	113	98 09	17
TYPED OR PRINTED		or maximum suprisonment of			910,000	ICER OR AUTHORIZE	I A PI	NUMBER	R	YEAR M	O DA

00078/980708-1359

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

* Flow is measured at least once ** heasured at least once per week.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont." for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. DISCHARGE MONITORING REPORT (DMR) 211 TP SBINE BLDG OMB No. 2040-0004 BEAVER VALLEY POWER STATION 12-161 Approval expires 05-31-98 (SUBE (5) ADDRESS P.O. BOX 4 PERMIT NUMBER DISCHARGE NUMBER ATTN: DAVID ORNDORF P - FINAL SHIPPINGPORT PA 15077 MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION FROM TO ### NO DISCHARGE NOTE: Read instructions before completing this form. ATTN: DAVID ORNDORF (20-21) (22-23) 124-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING 14 Card Only) QUANTITY OR CONCENTRATION (3 Card Only) FREQUENCY NO. PARAMETER SAMPLE (46-53) (54-61) (38-45) 146-531 154-611 OF EX TYPE (32-37) ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-631 (64-68) 169-701 李泰在李章 SAMPLE ***** GRAS 8.32 MEASUREMENT 00400 PERMIT 旅游物品旅游店 1000 **** 6.0 **日刊区区工事综合条件** 9.0 REQUIREMENT EFFLUENT GROSS VALU MINIBUS BALISON SAMPLE SULIDS, TOTAL GRAP MEASUREMENT 00530 1 0 0 PERMIT **** TO THE 安全会会会会 REQUIREMENT EFFLGENT GROSS VALU MO AVG DAILY MX SAMPLE OIL AND GREASE GRAR FREOR EXTR-GRAV HET MEASUREMENT PERMIT REQUIREMENT EFFLUENT GROSS VALU HO AVG DAILY MA IMST MAN MG/A SAMPLE FLOW. IN CONDUIT OF (03) EST, ,002 .007 MEASUREMENT 你立立立 PERMIT REEKLMESTIM EFFLUENT GROSS VALUE REQUIREMENT MO AVG DAILY MX MGD SAMPLE MEASUREMENT PERMIT

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER

Chemistry Manager
TYPED OR PRINTED

I CERTIFY UNDER PENALTY OF LAW THAT! HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C. \$ 1318. (Penalties under these statutes may include fines up to \$10,000 and or maximum impringenement of botween 6 months and 6 weeks.)

SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

REQUIREMENT
SAMPLE
MEASUREMENT
PERMIT
REQUIREMENT
SAMPLE
MEASUREMENT
PERMIT
REQUIREMENT

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "Q".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved." DISCHARGE MONITORING REPORT IDMRI UNIT 2 COOL TOWE DMB No. 2040-0004 NAME BEAFER VALLEY POWER STATION 12-161 117-191 Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) ATTN: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FIRAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION ** NO DISCHARGE FROM TO NOTE: Read instructions before completing this form. ATTN: DAVID GENDORF (20-21) (22-23) (24-25) 126-271 (28-29) (30-31) QUANTITY OR LOADING (3 Card Only) (4 Card Only) QUANTITY OR CONCENTRATION FREQUENCY NO. SAMPLE PARAMETER (46-53) (54-61) 138-451 146-531 154-611 EX TYPE (32-37) ANALYSIS AVERAGE MAXIMUM UNITS AVERAGE MINIMUM MAXIMUM UNITS (62-63) 164-681 (69-70) SAMPLE (12 MEASUREMENT PERMIT 200000 5.0 9.0 TWICEAGRAS EFFLUENT GROSS VALU REQUIREMENT BINIBUN MAKIMUM SU MONT SULIDS, TOTAL SAMPLE MEASUREMENT 00530 1 0 0 **医斯森斯斯斯** ***** **** ***** 100 PERMIT YWICE AGRAS EFFLUENT GROSS VALUEREQUIREMENT SO AVG DATLY BE HORT the six six six six six si 22222 OIL AND GREASE SAMPLE PREOR EXTR-GRAY MET MEASUREMENT 250225 to con PERMIT "WICE/GRAD EPFLUERT GROSS VALUEREQUIREMENT MO AYG DAILY NY MG/L 方口有工 造成去自己 京教 東京 京本 李华级李龙 FLOW, IN CONDUIT OR SAMPLE THRU THEATMENT PLAN MEASUREMENT 50050 1 0 0 REPORT REPORT **京李安安安安** 经验证证证证 京都京都市市 水冷水水 PERMIT TEEKLY ESTIF BEFLUERT GROSS VALO REQUIREMENT HC AVG DAILY MX MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON

TYPED OR PRINTED and or maximum imprisonment of between 6 months and 6 years.)

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

Chemistry Manager

MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING

THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33

U.S.C. § 1318. (Penalties under these statutes may include fines up to \$10,000

AREA

SIGNATURE OF PRINCIPAL EXECUTIVE

OFFICER OR AUTHORIZED AGENT

YEAR

DAY

MO

OF

393-5113

NUMBER

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "O".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across . .m in place of data entry
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Pr wipal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain coy for your records.
- More detailed instructions for use of this Discharge Monitoring P port (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

OMB No. 2040-0004 BRAVER VALLEY POWER STATION UNIT 2 AUX BOILE 12-16) Approval expires 05-39-98 ADDRESS P.O. BOX 4 (SUBR 05) PERMIT NUMBER DISCHARGE NUMBER ATTN: DAVID ORNDORF F - FINAL PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION FROM ¢¢¢ NO DISCHARGE TO NOTE: Read instructions before completing this form. ATTN: DAVID ORNDORP 120-21) 122-231 124-251 (26-27) (28-29) (30-31) 13 Card Only) QUANTITY OR LOADING 14 Card Ontvi QUANTITY OR CONCENTRATION FREQUENCY NO. PARAMETER SAMPLE (46-53) (54-61) (38-45) 146-531 (54-61) EX TYPE (32-37) ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-631 (64-68) (69-70) SOLIDS, TOTAL SAMPLE 1 19 **MEASUREMENT** PERMIT 杂杂类微杂类 事情中的意识 00530 1 0 0 30 100 MICENGEAS REQUIREMENT EFFLUENT GROSS VALU MO AVC DAILY BX BG/L HORT SAMPLE OIL AND GREASE MEASUREMENT FREOM EXTR-GRAV MET 00556 1 0 0 PERMIT te stra strate 在在在在在在 TWICENGRAB REQUIREMENT EFFLUENT GROSS VALU NO AYG DAILY MX MORT SAMPLE FLOW, IN CONDUIT OF (03) THEG TREATMENT PLAN MEASUREMENT 50050 1 0 0 PERMIT REPORT 新自立在政治 REEELTESTIE REQUIREMENT EFFLUENT GROSS VALUE EO AVG DAILY EX SGD SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 893-5113 0.9 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED NUMBER and or maximum imprisonment of between 6 months and 8 years.) OFFICER OR AUTHORIZED AGENT YEAR MO DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

Form Approved?

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Ervironmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Farameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" cuter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "\theta".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. DISCHARGE MONITORING REPORT (DMR) UNIT 1 OIL WATER OMB No. 2040-0004 BEAVER VALLEY POWER STATION (2-16) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) ATTH: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FIHAL SHIPPINGPORT PA 15077 MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION *** NO DISCHARGE FROM TO ATTR: DAVID ORNDORF NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) 126-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION 13 Card Only) (4 Card Only) FREQUENCY NO. PARAMETER SAMPLE (46-53) 154-611 (38-45) (46-53) 154-611 EX 132-371 TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-631 (64-68) (69-70) 南非政政政治方 SAMPLE 1 12 GRAA 7.13 MEASUREMENT 06400 1 0 0 PERMIT 5.0 EEEELW#在日直接 SFFLUENT GROSS VALU REQUIREMENT MINIMUM SUBLIAN 於在於在於在 STLIDS, TOTAL SAMPLE (19) MEASUREMENT 00530 1 0 0 **建设设施设施** 50 C TO TO TO TO TO *** 10 100 PERMIT EFFLUENT GROSS VALU REQUIREMENT NO AVG DAILY MY MG/I **运程取货**第1 非常意思必要 OIL AND GREASE SAMPLE < 5 25 GRAP FREON EXTR-GRAV MET MEASUREMENT 00556 1 0 0 PERMIT FERL BEFLUENT GROSS VALUEREQUIREMENT HO AVG DAILY BY BG/L 京原京市京大: 安存业等等 FLOW, IN CONDUIT OR SAMPLE EST. THRU TREATMENT PLAN MEASUREMENT **** 50050 1 0 0 REPORT 學學學學學學 中华华 PERMIT ESTIR EFFLUENT GROSS VALUEREQUIREMENT BO AYG DAILY BX SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

Chemistry Manager

TYPED OR PRINTED

THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33

U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000

and or maximum imprisonment of between 6 months and 5 years I

SIGNATURE OF PRINCIPAL EXECUTIVE

OFFICER OR AUTHORIZED AGENT

412

NUMBER

AREA

YEAR

09 117

DAY

MO

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period" (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "θ".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Con;" for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. . DISCHARGE MONITORING REPORT IDMRI OMB No. 2040-0004 BEAVER VALLEY POWER STATION 313 TURBINE BLOG 12-16) Approval expires 05-31-88 ADDRESS P.O. BOX 4 (SUBR 05) PERMIT NUMBER DISCHARGE NUMBER ATTW: DAVID ORNDORF F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY DAY YEAR MO DAY YEAR MO LOCATION FROM TO *** NO DISCHARGE NOTE: Read instructions before completing this form. ATTN: DAVID ORNDORF (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION 13 Card Only) (4 Card Only) FREQUENCY PARAMETER NO. SAMPLE (46-53) 154-611 (38-45) (46-53) 154-611 EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-631 (64-68) (59-70) SAMPLE GRAB 7,23 7.70 **MEASUREMENT** 最级激励自由 1 0 0 PERMIT 经存在证券在 6.0 3.0 EEKLIGRAS REQUIREMENT EFFLUENT GROSS VALU MAXIBUR SAMPLE SOLIDS. TOTAL GRAB 11.0 20.7 MEASUREMENT 00530 1 0 100 PERMIT REEFLYCHAR REQUIREMENT EFFLORET GROSS VALU MO AVG DAILY MM SAMPLE DIL AND GREASE 15.8 GRAB MEASUREMENT FREON EXTR-GRAV HET PERMIT **** 20 WEEKL GRES REQUIREMENT EPFLUENT GROSS VALU NO AVG DAILY MX FLOW. IN CONDUIT SAMPLE (03)EST. .002 .002 MEASUREMENT 章章教章章 表 华华古安全 李章章态态态 古古古古 PERMIT REQUIREMENT EFFLUENT GROSS VALUE DATLY MX MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE **MEASUREMENT** PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN: AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, ! BELIEVE THE SUBMITTED INFORMATION IS TRUE. ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 412 1393-5113 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1318. (Penalties under these statutes may include fines up to \$10,000 CODE TYPED OR PRINTED OFFICER OR AUTHORIZED AGENT NUMBER YEAR MO DAY and or maximum imprisonment of between 6 months and 6 years.) COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attechments here) Aux briler blowdown was discharged at a greatly reduced rate the first two weeks of August

EPA 313 due to maintenance activities.

00093/980708-1359

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental P. otection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Feriod", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under 'Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (sectual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

Legal Notice

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR) BEAVER VALLEY POWER STATION OMB No. 2040-0004 CHEM. FEED AREA (2-16) (17-15) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR 05) ATTM: DAVID ORNDORF PERMIT NUMBER DISCHARGE JUMBER F - FISAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION *** NO DISCHARGE FROM ATTN: DAVID ORNDORK NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (28-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OF CONCENTRATION 13 Card Onlyi 14 Card Only) FREQUENCY NO. PARAMETER SAMPLE (46-53) (54-61) 136-451 146-531 (54-61) EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) (69-70) 应应也还处: SAMPLE MEASUREMENT 00400 1 0 0 PERMIT REPORT 5.0 THICEAGRAE REQUIREMENT EFFLUENT GROSS VALU HINIMUM MAXIBUR KONT SOLIDS, TOTAL SAMPLE MEASUREMENT 00530 1 0 0 等 10. 发 20. 20. 20. 20. 10000 100 PERMIT "WICE GRAB EFFLUENT GROSS VALU REQUIREMENT BO AVG DAILY MR MORTI OIL AND GREASE SAMPLE PREON EXTR-GRAV MET MEASUREMENT 法法律法律法 PERMIT PRICEAGRAB REQUIREMENT EFFLUENT GROSS VALU EO AVG DAILY MX MONT FLOW, IN COMPUT OF 旅客店家店司 辛辛辛辛辛 森华森市市 SAMPLE (03) TARU TREATMENT PLAN MEASUREMENT 50050 1 0 0 REPORT **卫发育的原生** \$5 \$10 \$40 \$10 \$10 \$10 等等 是 是 双草草草草草草 古中东北 PERMIT RESELIESTIN EFFLUENT GROSS VALU REQUIREMENT DAILY NA NGD SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 393-5113 Chemistry Manager THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED OFFICER OR AUTHORIZED AGENT NUMBER YEAR MO DAY and or maximum imprisonment of between 6 months and 6 years.) COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

OF

00096/980708-1359

Form Approved."

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Pernut Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this *Discharge Monitoring Report (DMR)* form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved. " DISCHARGE MONITORING REPORT (DMR) BEAVER VALLEY POWER STATION CONDENSATE BLOWD OMB No. 2040-0004 12-16 Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBR OS) ATTN: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FIHAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION ** NO DISCHARGE FROM TO ATTH: DAVID ORNDORF NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) 126-271 (28-29) (30-31) QUANTITY OR LOADING (3 Cerd Only) (4 Cord Only) QUANTITY OR CONCENTRATION FREQUENCY NO. PARAMETER SAMPLE (46-53) 154-611 (38-45) (46-53) 154-61) EX 132-371 TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) (69-70) SAMPLE MEASUREMENT 00400 1 0 0 **追收收收收收** PERMIT **** 6.0 9.0 SEEKLIGHAB REQUIREMENT EFFLUENT GROSS VALU SAXIBUR SOLIDS, TOTAL SAMPLE 海南京南南: MEASUREMENT 泰拉克拉拉拉 中立立立 00530 1 0 0 おおおかなか PERMIT 政会改革等中 REEKLIGHAS REQUIREMENT EFFLUENT GROSS VALU MO AVG DAILY BE 李斯尔安尔 OIL AND GREASE SAMPLE 你你就就敢看 李章京歌春春 MEASUREMENT FREON EXTR-GRAV 00556 1 0 0 PERMIT WEEKLYGRAB REQUIREMENT EFFLUENT GROSS VALU MG/L BO AYG DAILY MX ***** MITHOGEN, AMMORIA SAMPLE 李华华李章 MEASUREMENT TOTAL (AS N) **建建筑实现 经过程数数**算数 *** **** PERMIT WEEKLYGRAD EFFLUERT GROSS VALU REQUIREMENT MO AVG DAILY BY MG/L 应查查查查查 李宗李宗李。 **** CLARTHOL CT-1, TOTA SAMPLE (19 WATER MEASUREMENT CARCOR **建设设建设设** PERMIT COMPZ EFFLUENT GROSS VALU REQUIREMENT NO AVG DAILY MX MG/L DISCHR **全年本本**中 京本原立方法 **市市市市市市** SAMPLE FLOW, IN CONDUIT OF THRU TREATMENT PLAN MEASUREMENT E 02 12 27 28 28 2222 PERMIT REFORT REPORT 100 Apr. 100 * EEKL TESTIM EFFLUENT GROSS VALU REQUIREMENT HO AVG DAILY MX 70744 CHLUNISE, TOTAL SAMPLE (19) MEASUREMENT **公司司司司**司 1000 なるななななな PERMIT 1 . 25 MEDELEGRAS EFFLUENT GROSS VALU REQUIREMENT MO AVG INST WAX MG/L NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON

TYPED OR PRINTED

MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 and or maximum imprisonment of between 6 months and 6 years.)

SIGNATURE OF PRINCIPAL EXECUTIVE

OFFICER OR AUTHORIZED AGENT

393-5113 AREA NUMBER

YEAR MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

HYDRAZING AND ANNONIA MONITORING TO APPLY DURING PERIODS OF MET LAYUP. REPORT THE DAILY MAXIMUM FOR BETZ D T-1 WHEN DISCHARGING (24 HR. COMP.): MG/L. (THE LIMIT IS 35 MG/L AS A DAILY MAX.)

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day av_rage as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter " equency of Analysis" both as "Sample Measurm at" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 23. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

DISCHARGE MONITORING REPORT (DMR) CONDENSATE BLOWD OMB No. 2040-0004 BEAVER VALLEY POWER STATION 12-161 Approval expires 05-31-98 ADDRESS P.O. BOY 4 (SUBR U5) PERMIT NUMBER DISCHARGE NUMBER ATTN: DAVID ORNDORF F - FINAL SHIPPIEGPORT Pa 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION ** NO DISCHARGE FROM TO NOTE: Read instructions before completing this form. ATTM: DAVID ORNDORF (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) 13 Card Only) QUANTITY OR LOADING 14 Card Only QUANTITY OR CONCENTRATION FREQUENCY PARAMETER NO. SAMPLE (46-53) (54-61) (38-45) (46-53) (54-61) EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) (69-70) HYDHAZINE SAMPLE 章 经 意 意 意 意 (19 MEASUREMENT 81313 1 0 0 PERMIT **** WEEKLEGRAB REQUIREMENT EFFLUENT GROSS VALU NO AVG DAILY MN MG/L SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS David Orndorf TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 412 393-5113 Chemistry Manager THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. 5 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1318. (Penalties under these statutes may include fines up to \$10,000 AREA TYPED OR PRINTED and or maximum imprisonment of between 6 months and 6 years.) OFFICER OR AUTHORIZED AGENT NUMBER YEAR MO DAY COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here) HYDRAZINE AND ANNONIA MONITORING TO APPLY DURING PERIODS OF WET LAYUP. REPORT THE DAILY MAXIMUM FOR BETZ D mg/L. (THE LIMIT IS 35 mg/L AS A DAILY MAX.) T-1 WHEN DISCHARGING (24 HR. COMP.):

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

00101/980708-1359

Form Approved.

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit. "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 40. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name/Location of Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved ... DISCHARGE MONITORING REPORT (DMR) BULK FUEL STORAG OMB No. 2040-0004 BEAVER VALLEY PORER STATION (2-16) Approval expires 05-31-98 ADDRESS P.O. BOX 4 (SUBE 05) PERMIT NUMBER DISCHARGE NUMBER ATTN: DAVID ORNDORF F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION TO ** NO DISCHERGE 1 ATTN: DAVID ORNDORP NOTE: Read instructions before completing this form. (20-21) (22-23) (24-25) (26-27) (28-29) (30-31) (3 Card Only) QUANTITY OR LOADING (4 Card Only) QUANTITY OR CONCENTRATION FREQUENCY PARAMETER NC. SAMPLE (46-53) (54-61) (38-45) (46-53) 154-611 EX (32-37) TYPE ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS (62-63) (64-68) 169-701 SAMPLE GRAB 8.22 MEASUREMENT 00400 1 0 0 PERMIT 6.0 9.0 REEKLYGEAS REQUIREMENT EFFLUENT GROSS VALU SINTAGE MAXIMUM SAMPLE SOLIDS, TOTAL <4 MEASUREMENT 00530 1 0 0 PERMIT REQUIREMENT EFFLUENT GROSS VALU HO AVG DAILY ME SAMPLE OIL AND GREASE < 5 < 5 PREON EXTR-GRAV MET MEASUREMENT 意意式が改立 PERMIT 专业企业企业 15 20 REQUIREMENT EFFLUENT CROSS VALU BC AVG DAILY MY FLOW, IN CONDUIT OR SAMPLE <.001 <.001 MEASUREMENT THRU TREATMENT PLAN 非常电影电影 PERMIT REQUIRE'MENT EFFLUENT GROSS VALU MG AVG DAILY ME MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN: AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 412:393-5113 Chemistry Manager THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

* Flow was monitored weekly; there was only flow during the last week of August.

and or maximum imprisonment of between 6 months and 5 years.)

TYPED OR PRINTED

OFFICER OR AUTHORIZED AGENT

NUMBER

00105/980708-1359

YEAR

MO

DAY

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some minor facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Erter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Enter each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period"; "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement: Finter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "0".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont," for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry
- 12. Enter "Name-Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice

PERMITTEE NAME/ADDRESS (Include Facility Name Location of Different) NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) Form Approved, DISCHARGE MONITORING REPORT (DMR) UNIT 1 GENRTE BLOMB No. 2040-0004 BEAVER VALLEY POWER STATION 12-161 Approval expires 05-31-98 ADDRESS P.D. BOX 4 (SUBR 05) ATTR: DAVID ORNDORF PERMIT NUMBER DISCHARGE NUMBER F - FINAL SHIPPINGPORT PA 15077 MAJOR MONITORING PERIOD FACILITY YEAR MO DAY YEAR MO DAY LOCATION ** NO DISCHARGE FROM TO ATTN: DAVID ORNDORF NOTE: Read instructions before completing this form. 120-21) 122-231 124-251 (26-27) (28-29) (30-31) QUANTITY OR LOADING QUANTITY OR CONCENTRATION (3 Card Only) 14 Card C FREQUENCY NO. PARAMETER SAMPLE (46-53) (54-61) (46-53) 136-51 154-611 EX TYPE (32-37) ANALYSIS AVERAGE MAXIMUM UNITS MINIMUM AVERAGE MAXIMUM UNITS 162-631 164-681 (69-70) SULIDS, TOTAL SAMPLE (19 MEASUREMENT 00530 1 建筑物物作品 食水丸丸 PERMIT WEEKLYGRAS EFFLUEST GROSS VALO REQUIREMENT SO AVE DAILY MN FLOW, IN CONDUIT OR SAMPLE THRU TREATMENT PLAN MEASUREMENT 50050 1 李松李芬春歌 华中北方 李章在立立立 PERMIT WEEKLYESTIM REQUIREMENT NO AVG DAILY MX MGD SAMPLE MEASUREMENT PERMIT REQUIREMENT I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND NAME/TITLE PRINCIPAL EXECUTIVE OFFICER TELEPHONE DATE AM FAMILIAR WITH THE INFORMATION SUBMITTED HEREIN; AND BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION, I BELIEVE THE SUBMITTED INFORMATION IS TRUE, ACCURATE AND COMPLETE. I AM AWARE THAT THERE ARE Chemistry Manager SIGNIFICANT PENALTIES FOR SUBMITTING FALSE INFORMATION, INCLUDING 393~5113 98 09 17 THE POSSIBILITY OF FINE AND IMPRISONMENT. SEE 18 U.S.C. \$ 1001 AND 33 SIGNATURE OF PRINCIPAL EXECUTIVE U.S.C. § 1319. (Penalties under these statutes may include fines up to \$10,000 AREA NUMBER TYPED OR PRINTED YEAR MO DAY and or maximum imprisonment of between 6 months and 5 years.) OFFICER OR AUTHORIZED AGENT COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

00108/980708-1359

OF

Public reporting burden for this collection of information is estimated to vary from a range of 10 hours as an average per response for some major facilities, to 110 hours as an average per response for some major facilities, with a weighted average for major and minor facilities of 18 hours per response, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the Earden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, SW Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

General Instructions

- 1. If form has been partially completed by preprinting, disregard instructions directed at entry of that information already preprinted.
- 2. Enter "Permittee Name/Mailing Address (and facility name/location, if different)," "Permit Number," and "Discharge Number" where indicated. (A separate form is required for each discharge.)
- 3. Enter dates beginning and ending "Monitoring Period" covered by form where indicated.
- 4. Eater each "Parameter" as specified in monitoring requirements of permit.
- 5. Enter "Sample Measurement" data for each parameter under "Quantity" and "Quality" in units specified in permit.
 "Average" is normally arithmetic average (geometric average for bacterial parameters) of all sample measurements for each parameter obtained during "Monitoring Period", "Maximum" and "Minimum" are normally extreme high and low measurements obtained during "Monitoring Period." (Note to municipals with secondary treatment requirement. Enter 30-day average of sample measurements under "Average," and enter maximum 7-day average of sample measurements obtained during monitoring period under "Maximum.")
- 6. Enter "Permit Requirement" for each parameter under "Quantity" and "Quality" as specified in permit.
- 7. Under "No Ex" enter number of sample measurments during monitoring period that exceed maximum (and/or minimum or 7-day average as appropriate) permit requirement for each parameter. If none, enter "O".
- 8. Enter "Frequency of Analysis" both as "Sample Measurment" (actual frequency of sampling and analysis used during monitoring period) and as "Permit Requirement" specified in permit. (e.g., Enter "Cont." for continuous monitoring, "1/7" for one day per week, "1/30" for one day per month, "1/90" for one day per quarter, etc.)
- 9. Enter "Sample Type" both as "Sample Measurement" (actual sample type used during monitoring period) and as "Permit Requirement," (e.g., Enter "Grab" for individual sample, "24HC" for 24-hour composite, "N/A" for continuous monitoring, etc.)
- 10. Where violations of permit requirements are reported, attach a brief explanation to describe cause and corrective actions taken, and reference each violation by date.
- 11. If "no discharge" occurs during monitoring period, enter "No Discharge" across form in place of data entry.
- 12. Enter "Name/Title of Principal Executive Officer" with "Signature of Principal Executive Officer of Authorized Agent," "Telephone Number," and "Date" at bottom of form.
- 13. Mail signed Report to Office(s) by date(s) specified in permit. Retain copy for your records.
- 14. More detailed instructions for use of this Discharge Monitoring Report (DMR) form may be obtained from Office(s) specified in permit.

Legal Notice