PDR-016



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

JAN 22 1986

Ms. Daurice C. Morrow Fried, Frank, Harris, Shriver & Jacobson 600 New Hampshire Avenue, NW, Suite 1000 Washington, DC 20037

IN RESPONSE REFER TO FOIA-85-782

Dear Ms. Morrow:

This is in further response to your letter dated November 25, 1985, in which you requested, pursuant to the Freedom of Information Act, seven categories of documents.

The documents listed on the enclosed Appendix C are being placed in the NRC Public Document Room (PDR), 1717 H Street, NW, Washington, DC.

The documents listed on the enclosed Appendix D are already available in the PDR.

This completes NRC's action on categories one and three of your request. The search for and review of additional documents subject to the other categories of your request are continuing. As soon as our efforts are completed, we will notify you.

Sincerely,

Donnie H. Brindley

Donnie H. Grimsley. Director Division of Rules and Records Office of Administration

Enclosures: As stated

Re: FOIA-85-782

APPENDIX C

1. 03/13/72 Letter to B. Lee from R. Boyd re: Request for information concerning the structural safety in the tori. (1 page)

2. 03/27/72 Letter to R. Boyd from W. Stiede re: Structural integrity of the Quad-Cities Tori. (1 page)

APPENDIX D

1. 05/29/72	Reportable Occurrence-Torus suction header discovered to have
	hanger damage and was displaced from normal position-caused by
	four hanger bolts failing. (Accession No. 8304070014)

- 05/30/72 Reportable Occurrence same subject as above. (Accession No. 8304070033)
- 3. 05/31/72 Reportable Occurrence Additional information to supplement 3/27/72 letter. (Accession No. 8305190087)
- 4. 10/26/72 Special Report 5 Torus Ring Header Support Failure. (Accession No. 8304060538)