



Log # TXX-88458
File # 10110
910.4
Ref. # 10CFR50.55(e)

May 13, 1988

William G. Council
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION
DOCKET NOS. 50-445 AND 50-446
TURBINE DRIVEN AUXILIARY FEEDWATER PUMP BEARING TEMPERATURE
SDAR: CP-87-50 (SUPPLEMENTAL REPORT)

Gentlemen:

On July 27, 1987, we verbally notified your Mr. H. S. Phillips of a deficiency involving abnormal thrust bearing temperatures on the Turbine Driven Auxiliary Feedwater Pump. Our last report, logged TXX-88392 dated April 15, 1988, provided a schedule for the completion of corrective actions to resolve this deficiency. Due to continuing delays in supply of material and repair instructions by the vendor, the schedule provided in TXX-88392 will not be met. The new schedule date for completion, based upon projected availability of spare parts and finalized repair instructions from the vendor, is November 14, 1988 for all Unit 1 AFW Pumps. The completion schedule for Unit 2 will be prior to Unit 2 fuel load.

Very truly yours,

W. G. Council

W. G. Council

By: *D. R. Woodlan*

D. R. Woodlan
Docket Licensing Manager

MCP/grr

c-Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8805130095 880513
PDR ADOCK 05000445
S DCD

JE27
10