

September 29, 1998


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Docket No. 50-361 and 50-362  
Revised 30-Day Report  
Licensee Event Report No. 2-1998-012-01  
San Onofre Nuclear Generating Station, Units 2 and 3

This submittal provides the updated 30-day written Licensee Event Report (LER) for an occurrence involving a component cooling system pressure relief valve being set above its required relief setpoint. Neither the health nor the safety of plant personnel or the public was affected by this occurrence or condition.

Any actions listed are intended to ensure continued compliance with existing commitments as discussed in applicable licensing documents; this LER contains no new commitments. If you require any additional information, please so advise.

Sincerely,



Enclosure: LER No. 2-1998-012-01

cc: E. W. Merschoff, Regional Administrator, NRC Region IV  
J. A. Sloan, NRC Senior Resident Inspector, Units 2 and 3  
J. W. Clifford, NRC Project Manager, San Onofre Units 2 and 3  
Institute of Nuclear Power Operations (INPO)

9810070126 980929  
PDR ADOCK 05000362  
S FDR

IE28/