DCD

MAY 0 4 1988

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

The NRC recently received an anonymous call concerning snubber worker training irregularities. These irregularities allegedly occurred on or before March 14, 1988, and concerned contractors who were going to be working on safety-related snubbers.

Allegedly, those contract employees failed a qualification test. The tests were re-evaluated and plant specific questions were deleted allowing the contractors to pass. The above concern is provided to you for your followup. Please provide to this office, within 30 days of the date of this letter, a description of the actions you have taken and results achieved.

We will gladly discuss any questions you have concerning this information.

Sincerely,

ORIGINAL STORED BY W. C. OULDRACOND

Edward G. Greenman, Director Division of Reactor Projects

cc: L. Storz, Plant Manager DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Harold W. Kohn, Ohio EPA James W. Harris, State of Ohio Robert M. Quillin, Ohio Department of Health State of Ohio, Public Utilities Commission

DCD

