

SALP BOARD REPORT

---

U.S. NUCLEAR REGULATORY COMMISSION  
REGION III

---

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

50-456/88001; 50-457/88001  
Inspection Report No.

Commonwealth Edison Company  
Name of Licensee

Braidwood Station  
Name of Facility

December 1, 1986 through December 31, 1987  
Assessment Period

A. Summary of Meeting with Commonwealth Edison Company on April 5, 1988

The findings and conclusions of the SALP Board documented in Inspection Report Nos. 50-456/88001; 50-457/88001 were discussed with the licensee on April 5, 1988, at the Braidwood Station Training Building. The licensee's regulatory performance was presented and found acceptable in each functional area.

The following individuals attended the meeting:

Commonwealth Edison Company

C. Reed, Senior Vice President, Nuclear Operations  
T. J. Maiman, Vice President, PWR Operations  
L. DeGeorge, Assistant Vice President, Licensing and Technical Support  
K. L. Graesser, General Manager, PWR Operations  
K. L. Kofron, Production Superintendent, Braidwood  
S. C. Hunsader, Nuclear Licensing Administrator  
P. L. Barnes, Regulatory Assurance Supervisor  
R. E. Aker, Radiation/Chemistry Supervisor, Braidwood  
L. E. Davis, Assistant Superintendent, Technical Services  
G. R. Masters, Assistant Superintendent, Operations  
R. C. Ward, Services Superintendent, Byron  
D. E. Paquette, Assistant Superintendent, Maintenance  
G. Vanderheyden, Operations Training Supervisor  
R. Legner, Senior Operating Engineer  
R. A. Flessner, Administrative Engineer, PWR Operations  
D. Demos, Joliet District Superintendent  
G. W. Nelson, Assistant Technical Staff Supervisor  
B. R. Shelton, PWR Engineering Manager  
M. E. Lohmann, Project Construction and Startup Superintendent  
R. D. Kyrouac, Station Quality Assurance Superintendent  
H. P. Studtmann, Director of Quality Assurance (Maintenance)

U. S. Nuclear Regulatory Commission, Region III

C. J. Paperiello, Deputy Regional Administrator  
E. G. Greenman, Director, Division of Reactor Projects  
R. M. Lickus, Chief, State and Government Affairs  
W. L. Forney, Chief, Reactor Projects Branch 1  
J. M. Hinds, Jr., Chief, Reactor Projects Section 1A  
T. M. Tongue, Senior Resident Inspector, Braidwood  
T. E. Taylor, Resident Inspector, Braidwood  
G. A. Van Sickle, Project Inspector, Reactor Projects Section 1A

B. Comments Received from Licensee

In a telephone conversation with G. A. Van Sickle of the NRC on May 5, 1988, P. L. Barnes, Braidwood Regulatory Assurance Supervisor, stated that Commonwealth Edison has no comments addressing the specific content of the report. Because there are no comments, this appendix contains no changes to the SALP Report.

C. Regional Administrator's Conclusions Based on Consideration of Licensee Comments

Braidwood's overall ratings in all functional areas have not changed.