September 15, 1988

X Not Applicable

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE -- PNO-1V-88-76A

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region IV staff on this date.

FACILITY: Wolf Creek Nuclear Operating Corp.
Wolf Creek
Burlington, Kansas
Docket No. 50-482

Licensee Emergency Classification:
Notification of Unusual Event
Alert
Site Area Emergency
General Emergency

SUBJECT: PERSONNEL ELECTROCUTION UPDATE

This provides updated information on the electrocution that occurred at Wolf Creek or September 13, 1988. The contract electrician was working with a crew of four electricians which included a supervisor. A cable was going to be pulled to a lighting circuit panel through a conduit and junction box. The decision was apparently made to conduct the work with other cables in the box energized. Fire seals had to be removed from the conduit in order to install the additional cable. The electrician was standing on piping and leaning across a ventilation duct to perform the work. The conduit was disconnected at the junction box in order to remove the fire seal. The movement of the conduit apparently cut an energized cable and the junction box became energized. The electrician's contact with the energized junction box and the ventilation duct apparently caused the electrocution. The licensee is continuing investigation of this event and the resident inspectors are monitoring licensee actions.

The NRC has responded to news media inquiries.

The licensee has issued a press release.

Region IV has notified OSHA.

Region IV received notification of this occurrence from the resident inspector at Wolf Creek at 2 p.m. (CDT) on September 13, 1988. Region IV has informed NRR.

This information has been confirmed with a licensee representative.

CONTACT: D. Chamberlain FTS 728-8249

RIV:C:PSA DDChamberlain;df 9/15/88 D:DRP LJCallan 9/15/88

RA (W) RDMartin 9/15/88

8809190141 880915 PDR 1&E PNO-IV-88-86A PDC