Docket Nos:

A RESOURCE ENGINEERING COMPANY 896 VIRGINIA AOAD. CONCORD MA 01742. (617) 369-891

SEP 16 1988 1 U. S. NUCLEAR REGULATORY COMMISSION NIESS

Mail Section

ERT Project No.: 5990-002 ERT Ref. No.: 51-REH-302

environmental and engineering excellence

September 8, 1988

Mr. Leland C. Rouse, Chief Fuel Cycle Safety Branch Division of Industrial and Medical Nuclear Safety, NMSS U.S. Nuclear Regulatory Commission Washington, D. C. 20555

Radiological Surveys of Shieldalloy's Cambridge, Ohio and Newfield. New Jersey Sites

Dear Mr. Rouse:

Shieldalloy Metallurgical Corporation has provided us with your letter of July 27, 1988 enclosing the Oak Ridge Associated Univesities (ORAU) survey report of Shieldalloy's Cambridge facility along with the results of your staff roview. ERT has been commissioned to plan a comprehensive Ladiological survey of the site as required by the enclosure of your letter.

DOCKETED

USNRC

SEP 1 6 1988 )

NMSS

MAIL SECTION DOCKET CLERK

Shieldalloy has also forwarded to ERT a copy of the survey report of Shialdalloy's Newfield facility prepared by ORAU and sent by Mr. John Kinneman of Region I on August 9, 1988. ERT has been asked to prepare a plan in order to clean up the Newfield site where radiologically necessary. As part of this plan, we are preparing an outline for a radiological survey to be conducted at the facility after completion of the cleanup activities in order to monitor the effectiveness of the cleanup operation.

8809200241 880908

additional information

Mr. Leland C. Rouse, Cheif Page Two September 8, 1988

It is desirable that the two surveys for Newfield and Cambridge match the techniques and principles used by your consultant ORAU. We therefore propose to visit with Mr. J. D. Berger of ORAU on September 19, 1988 in order to obtain his informal technical input to our survey outlines. We would appreciate your indicating your agreement to this visit by return telecopy. Our telecopy number is 508-369-6721.

Sincerely yours,

Dr. Raymond E. Holmes

Vice President Chief Engineer

REH/r

cc: Mr. George T. Campbell - Shieldalloy

Mr. John Fillo - ERT

DOCKET NO. 40-7102 & 40-8948

CONTROL NO. 2473?

DATE OF DOC. Sept. 8, 1988

DATE ROVD. Sept. 16, 1988

FOUR POR

ISEREF. SAFEGUARDS

DATE 9/1488

INIT AL SOU