

JAN 30 1986

License No. 37-20932-01  
Docket No. 030-29003  
Control No. 104595

Emkey-Weisberg-Greth Arthritis Associates, Inc.  
ATTN: Ronald D. Emkey, M.D.  
401 Buttonwood Street  
West Reading, Pennsylvania 19611

Gentlemen:

Please find enclosed your NRC material license.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the Region I Material Licensing Section, (215) 337-5239, so that we can provide appropriate corrections and answers.

Please be advised that you must conduct your program involving licensed radioactive materials in accordance with the conditions of your NRC license, representations made in your license application, and NRC regulations. In particular, please note the items in the enclosed, "Requirements for Materials Licensees."

Please note that License Condition 14A. authorizes you to leak test the Gadolinium 153 sealed source at intervals not to exceed 1 year; however, the Iodine 125 sealed source will still have to be leak tested at intervals not to exceed 6 months.

Since serious consequences to employees and the public can result from failure to comply with NRC requirements, the NRC expects licensees to pay meticulous attention to detail and to achieve the high standard of compliance which the NRC expects of its licensees.

You will be periodically inspected by NRC. A fee may be charged for inspections in accordance with 10 CFR Part 170. Failure to conduct your program safely and in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in prompt and vigorous enforcement action against you. This could include issuance of a notice of violation, or in case of serious violations, an imposition of a civil penalty or an order suspending, modifying or revoking your license as specified in the General Policy and Procedures for NRC Enforcement Actions, 10 CFR Part 2, Appendix C.

OFFICIAL RECORD COPY

ML 37-20932-01/LTR - 0001.0.0  
01/27/86

8603070609 860130  
REQ1 LIC30  
37-20932-01 PDR

ML10

We wish you success in operating a safe and effective licensed program.

Sincerely,

Original Signed By:

Jack Davis

Jack Davis

Nuclear Materials Safety Section A


Division of Radiation Safety

and Safeguards

Enclosures:

1. License No. 37-20932-01
2. Requirements for Materials Licensees
3. NRC Forms 3 and 313M
4. 10 CFR Parts 2, 19, 20, 30, and 170

RI:DRSS  
Davis/mlb  
01/28/86

  
RI:DRSS  
Kinneman  
01/29/86

OFFICIAL RECORD COPY

ML 37-20932-01/LTR - 0002.0.0  
01/27/86

1/15/86

TELEPHONE OR VERBAL CONVERSATION RECORD

TIME

☐ A.M.  
☐ P.M.

☐ INCOMING CALL

☐ OUTGOING CALL

☐ VISIT

PERSON CALLING

Jack Davis

OFFICE/ADDRESS

RI

PHONE NUMBER

EXTENSION

PERSON CALLED

Jim Nicolosi

OFFICE/ADDRESS

Hydro Nuclear

PHONE NUMBER

EXTENSION

609-596-0098

CONVERSATION

SUBJECT

Re: Emkey - Weissberg - Greth - Arthritis Assoc Application

SUMMARY

for Bone Mineral Analyzer.

Leah Test procedure outlined in Dec 6, 1985 letter does not contain sufficient information to authorize the license to perform 4T of sealed source (Gd 153).

Will submit addendum by <sup>Dr. S.</sup> to confirm the licensee will use Seimens Gamma Series Leah TEST Kit Model QT1 (4N-12-00369-01) (Analysis by Seimens).

Region III confirmed Seimens is authorized for 1kit and to analyze samples -

Also will Request 4T annually (Lunar) not ~~every~~ 6 months.

REFERRED TO:

ACTION REQUESTED

ACTION TAKEN

☐ ADVISE ME OF ACTION TAKEN.

INITIALS

DATE

INITIALS

DATE

"OFFICIAL RECORD COPY"

ML10