October 6, 1998

Mr. D. R. Gipson Senior Vice President Nuclear Generation The Detroit Edison Company 6400 North Dixie Highway Newport, MI 48166

SUBJECT: NRC RADIATION PROTECTION INSPECTION REPORT 50-341/98016(DRS)

Dear Mr. Gipson:

On September 18, 1998, the NRC completed an inspection at your Enrico Fermi, Unit 2 facility. The enclosed report presents the results of that inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety, to compliance with the Commission's rules and regulations, and with the conditions of your license. The purpose of this inspection was to review the as-low-as-is-reasonably-achievable (ALARA) planning and controls for your sixth refueling outage (RFO6); internal exposure monitoring; radiological surveys and postings; radiation worker performance; and the control of high, locked high and very high radiation areas. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations of activities and equipment materiel condition, and interviews with personnel.

No violations of NRC requirements were identified.

Effective ALARA planning and controls were implemented for those RFO6 activities observed during this inspection. The internal exposure program was well implemented and radiological postings, radiation protection technician job coverage and worker performance were considered good. High, locked high, and very high radiation areas were also well controlled. However, some problems were observed with housekeeping and material condition inside the waste clarifier tank room, with radiological access control between the Reactor and Turbine buildings and with some workers' whole body frisking practices. These problems were being corrected by your staff during the inspection.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response to this letter will be placed in the NRC Public Document Room (PDR).

9810130099 981006 PDR ADOCK 05000341 G PDR D. Gipson

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original /s/ S. A. Reynolds for

John A. Grobe, Director Division of Reactor Safety

Docke: No.: 50-341 License No.: NPF-43

Enclosure: Inspection Report 50-341/98016(DRS)

cc w/encl:

P. Marquardt, Corporate Legal Department R. Gaston, Compliance Supervisor R. Whale, Michigan Public Service Commission Michigan Department of Environmental Quality Monroe County, Emergency Management Division

N. Peterson, Director, Nuclear Licensing

Emergency Management Division, MI Department of State Police

Distribution:

CAC (E-Mail) RPC (E-Mail) Project Mgr., NRR w/encl J. Caldwell, RIII w/encl C. Pederson, RIII w/encl B. Clayton, RIII w/encl SRI Fermi w/encl DRP w/encl TSS w/encl DRS (2) w/encl IFOLD RIII PRR w/encl PUBLIC-IE-01 w/encl Docket File w/encl GREENS IEO (E-Mail) DOCDESK (E-Mail)

DOCUMENT NAME: G:DRS\FER980

OFFICE	RIII	RIII	E	RIIM	N	RIII
NAME	Shah/Mitchell	Shear 6LS		Buidess	The second s	Grobe Th
DATE	10/1 /98	10/5/98		10/ 6/98		10/ 6/98

OFFICIAL RECORD COPY

090021