



May 9, 1988
NRC-88-0139

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

- References: 1) Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43
- 2) NRC Compliance Bulletin No. 88-03, "Inadequate Latch Engagement in HFA Type Latching Relays Manufactured by General Electric (GE) Company."


Subject: Response to NRC Bulletin No. 88-03

In response to the NRC Bulletin No. 88-03 (Reference 2), Detroit Edison Company hereby provides information requested regarding GE HFA type latching relays.

These HFA type latching relays manufactured by General Electric are not used at Fermi 2.

If you have any questions, please contact Mr. Girija Shukla at (313) 586-4270.

Sincerely,


B. Ralph Sylvia
Senior Vice President

cc: A. B. Davis
R. C. Knop
T. R. Quay
W. G. Rogers
USNRC Region III