



Gary R. Peterson
Vice President

Duke Energy Corporation

Catawba Nuclear Station
4800 Concord Road
York, SC 29745

(803) 831-4251 OFFICE
(803) 831-3426 FAX

October 6, 1998


U. S. Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Duke Energy Corporation
Catawba Nuclear Station Unit 2
Docket No. 50-414
Licensee Event Report 414/1998-004-00

Attached please find Licensee Event Report 414/98-004-00
entitled Error During Tagout Causes De-Energization of Vital
Bus and Actuation of Low Temperature Overpressure
Protection. Commitments are contained in the Planned
Corrective Action section of the attached report.

Questions regarding this Licensee Event Report should be
directed to M. H. Chernoff at (803) 831-3414.

Sincerely,



G. R. Peterson

Attachment

Handwritten initials: JH

9810140081 981006
PDR ADOCK 0500C414
S PDR

U.S. Nuclear Regulatory Commission
October 5, 1998
Page 2

xc:

L. A. Reyes
U. S. Nuclear Regulatory Commission
Regional Administrator, Region II
Atlanta Federal Center
61 Forsyth St., SW, Suite 23T85
Atlanta, GA 30303

P. S. Tam
NRC Senior Project Manager (CNS)
U. S. Nuclear Regulatory Commission
Mail Stop O-14H25
Washington, DC 20555-0001

D. J. Roberts
Senior Resident Inspector (CNS)
U. S. Nuclear Regulatory Commission
Catawba Nuclear Site