



October 2, 1998

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

Subject:

Docket Nos. 50-361 and 50-362

Revised 30-Day Report

Licensee Event Report No. 1998-006-01

San Onofre Nuclear Generating Station, Units 2 and 3

By letter dated May 21, 1998, SCE provided LER 1998-006 for an event involving missed Technical Specification surveillances due to a procedural error. Because this occurrence was applicable to both operating units, a single report for Unit 2 was submitted in accordance with NUREG-1022, Rev. 1. SCE is submitting this revised report to provide additional information regarding missed TS surveillances.

Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

Any actions listed are intended to ensure continued compliance with existing commitments as discussed in applicable licensing documents; this LER contains no new commitments. If you require any additional information, please so advise.

If your require any additional information, please so advise.

9810140280 981002 PDR ADDCK 05000361

CC:

Enclosure: LER No. 1998-006-01

E. W. Merschoff, Regional Administrator, NRC Region IV

J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units 2 & 3

J. W. Clifford, NRC Project Manager, San Onofre Units 2 & 3 Institute of Nuclear Power Operations (INPO)

P. O. Box 128 San Clemente, CA 92674-0128 714-368-6255 Fax 714-368-6183 1/1 ser