Docket No. 50-271

Vermont Yankee Nuclear Power Corporation ATTN: Mr. Warren P. Murphy

Vice President and Manager of Operations

RD 5, Box 169 Ferry Road Brattleboro, Vermont 05301

Gentlemen:

Subject: Inspection Report No. 50-271/86-03

A routine inspection was conducted on February 3-6, 1986 by Ms. Jean A. Cioffi and Mr. Henry J. Bicehouse of the Vermont Yankee Nuclear Power Plant, related to the implementation of radiological controls during the piping replacement outage. In general, the program in place for controlling radiologically significant work during the current outage operations was found to be well-established and implemented.

Within the scope of this inspection, no violations or deviations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Stened Dy:

Division of Radiation Safety and Safeguards

Enclosure: NRC Region I Inspection Report No. 50-271/86-03

cc w/enc1:

R. W. Capstick, Licensing Engineer

W. F. Conway, President and Chief Executive Officer

J. P. Pelletier, Plant Manager
Donald Hunter, Vice President
Cort Richardson, Vermont Public Interest Research Group, Inc.
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of New Hampshire
State of Vermont

OFFICIAL RECORD COPY

IR VY 86-03 - 0001.0.0 02/28/86 JECK

bcc w/encl:
Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o encl)
Section Chief, DRP
M. McBride, RI, Pilgrim
H. Eichenholz, SRI, Yankee
V. Rooney, LPM, NRR

RI:DRSS Cioffi/ca/ms 2/3/86

gic

RI:DRSS Bicehouse 3/3 /86 SAD RIJORSS Shanbaky 3/3/86 MRT DRSS Bellamy 3/3/86

R1:DR85 Mantin 2/ /86

OFFICIAL RECORD COPY

IR VY 86-03 - 0002.0.0 02/28/86