

September 15, 1988

Docket No. 50-267

Mr. R. O. Williams, Jr.
Vice President, Nuclear Operations
Public Service Company of Colorado
Post Office Box 840
Denver, Colorado 80201-0840

Dear Mr. Williams:

SUBJECT: CORRECTION TO AUGUST 30, 1988 LETTER

We have noted that Enclosure 1 to our letter of August 30, 1988 concerning the Fort St. Vrain schedule commitment items was incorrect. We have enclosed a correct version of Enclosure 1 with this letter. We apologize for problems caused by this error.

Sincerely,

/s/

Kenneth L. Heitner, Project Manager
Project Directorate - IV
Division of Reactor Projects - III,
IV, V and Special Projects

Enclosure:
As stated

cc w/enclosure:
See next page

DISTRIBUTION

Docket File
L. Rubenstein
OGC-Rockville
PD4 Plant File

NRC PDR
J. Calvo
E. Jordan

Local PDR
P. Noonan
B. Grimes

PD4 Reading
K. Heitner
ACRC (10)

PD4/LA *RH*
PNoonan
09/15/88

PD4/PM *RH*
KHeitner:sr
09/15/88

PD4/D *MC*
JCalvo
09/15/88

8809230055 880915
PDR ADOCK 05000267
P PDC

DF01
1/1

September 15, 1988

Docket No. 50-267

Mr. R. O. Williams, Jr.
Vice President, Nuclear Operations
Public Service Company of Colorado
Post Office Box 840
Denver, Colorado 80201-0840

Dear Mr. Williams:

SUBJECT: CORRECTION TO AUGUST 30, 1988 LETTER

We have noted that Enclosure 1 to our letter of August 30, 1988 concerning the Fort St. Vrain schedule commitment items was incorrect. We have enclosed a correct version of Enclosure 1 with this letter. We apologize for problems caused by this error.

Sincerely,

/s/

Kenneth L. Heitner, Project Manager
Project Directorate - IV
Division of Reactor Projects - III,
IV, V and Special Projects

Enclosure:
As stated

cc w/enclosure:
See next page

DISTRIBUTION

Docket File
L. Rubenstein
OGC-Rockville
PD4 Plant File

NRC PDR
J. Calvo
E. Jordan

Local PDR
P. Noonan
B. Grimes

PD4 Reading
K. Heitner
ACRS (10)

PD4/LA *92H*
PNoonan *sr*
09/15/88

PD4/PM *92H*
KHeitner:sr
09/15/88

PD4/D *MAC*
JCalvo
09/15/88



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

September 15, 1988

Docket No. 50-267

Mr. R. C. Williams, Jr.
Vice President, Nuclear Operations
Public Service Company of Colorado
Post Office Box 840
Denver, Colorado 80201-0840

Dear Mr. Williams:

SUBJECT: CORRECTION TO AUGUST 30, 1988 LETTER

We have noted that Enclosure 1 to our letter of August 30, 1988 concerning the Fort St. Vrain schedule commitment items was incorrect. We have enclosed a correct version of Enclosure 1 with this letter. We apologize for problems caused by this error.

Sincerely,

A handwritten signature in cursive script that reads "Kenneth L. Heitner".

Kenneth L. Heitner, Project Manager
Project Directorate - IV
Division of Reactor Projects - III,
IV, V and Special Projects

Enclosure:
As stated

cc w/enclosure:
See next page

Mr. R. O. Williams, Jr.
Public Service Company of Colorado

Fort St. Vrain

cc:

Mr. D. W. Warembourg, Manager
Nuclear Engineering Division
Public Service Company
of Colorado
P. O. Box 840
Denver, Colorado 80201-0840

Albert J. Hazle, Director
Radiation Control Division
Department of Health
4210 East 11th Avenue
Denver, Colorado 80220

Mr. David Alberstein, 14/159A
GA Technologies, Inc.
Post Office Box 85608
San Diego, California 92138

Mr. R. O. Williams, Jr., Acting Manager
Nuclear Production Division
Public Service Company of Colorado
16805 Weld County Road 19-1/2
Platteville, Colorado 80651

Mr. H. L. Brey, Manager
Nuclear Licensing and Fuel Division
Public Service Company of Colorado
P. O. Box 840
Denver, Colorado 80201-0840

Mr. P. F. Tomlinson, Manager
Quality Assurance Division
Public Service Company of Colorado
16805 Weld County Road 19-1/2
Platteville, Colorado 80651

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 640
Platteville, Colorado 80651

Mr. R. F. Walker
Public Service Company of Colorado
Post Office Box 840
Denver, Colorado 80201-0840

Kelley, Stansfield & O'Donnell
Public Service Company Building
Room 900
550 15th Street
Denver, Colorado 80202

Commitment Control Program
Coordinator
Public Service Company of Colorado
2420 W. 26th Ave. Suite 100-D
Denver, Colorado 80211

Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Chairman, Board of County Commissioners
of Weld County, Colorado
Greeley, Colorado 80631

Regional Representative
Radiation Programs
Environmental Protection Agency
1 Denver Place
999 18th Street, Suite 1300
Denver, Colorado 80202-2413

PUBLIC SERVICE COMPANY OF COLORADO COMMITMENTS
RELATED TO THE OPERATION OF THE
FORT ST. VRAIN NUCLEAR GENERATING STATION

<u>Item</u>	<u>Commitment Description/Requirement</u> (Reference)	<u>Schedule</u>
1.	Provide status reports on the Nuclear Performance Enhancement Program on an annual basis. (P-88031)	Approximately annually
2.	Implement the Technical Specifications (TS) Upgrade Program (P-85098):	
a.	Provide a revised final draft proposal of the Upgraded TS for NRC comment, (P-87063)	Complete
b.	Submit a license amendment to incorporate the Upgraded TS, (P-85243)	90 days after NRC comments on Item 2a
c.	Implement the Upgraded TS. (P-85243)	Approximately 4th refueling outage (License amendment will define)
3.	Improve control rod and reserve shutdown reliability. Incorporate the interim Technical Specifications in the Upgrade Program.	(See Item 2)
4.	Develop a plan to implement approved modifications to control moisture ingress and submit annual reports on progress. (P-85022 and P-85082)	Annually
5.	Evaluate control of moisture in CRDM purge system. (P-85021)	4th refueling outage
6.	PCRV Tendon Surveillance Requirements:	
a.	Incorporate the revised Tendon Surveillance Program into the Technical Surveillance (P-85199),	(See Item 2)
b.	Provide the results of the revised program to the NRC.	Approximately annually

7. Provide an improved CRDM surveillance program which includes consideration of CRDM operational testing. (P-88012)

Five months
after the start
of 4th refueling
outage

8. Fire Protection Modifications:

a. Perform emergency lighting modifications (P-88030)

Complete by 3/1/88

b. Perform modifications involving ACM backfeed, permanent turbine water removal pump, and valve operability (P-87013).

Startup following
4th refueling
outage