

Michael P. Gallagher, P.E. Plant Manager Limerick Generating Station

PECO Energy Company Limerick Generating Station PO Box 2300 Sanatoga, PA 19464-0920 610 718 2000

10CFR50.73

October 9, 1998

Docket Nos. 50-352 50-353 License No. NPF-39 NPF-85

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

SUBJECT: Licensee Event Report Limerick Generating Station - Units 1 and 2

This LER reports a condition outside the design basis of the plant and a violation of License Condition 2.C.(3) in that local emergency diesel generator control may not be available to support safe shutdown of the plant in the event of a fire due to fire-induced damage of associated control cables.

Reference:	Docket
Report Number: Revision Number: Discovery Date: Report Date: Facility:	1-98-0 00 Septem Octobe Limeri
	P.O. E


Docket Nos. 50-352 50-353 1-98-018 00 September 11, 1998 October 9, 1998 Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464-2300

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(ii)(B) and License Conditions 2.F and 2.E for Units 1 and 2, respectively.

Sincerely,

michael Sally

cc: H. J. Miller, Administrator Region I, USNRC A. L. Burritt, USNRC Senior Resident Inspector, LGS



Terr