

May 17, 1988

Docket No.: 50-293

Mr. Ralph G. Bird
Senior Vice President - Nuclear
Boston Edison Company
800 Boylston Street
Boston, Massachusetts 02199

Dear Mr. Bird:

SUBJECT: PTLGRIM SAFETY EVALUATION OF FIRE DOOR-TO-FRAME, FRAME-TO-WALL
AND ANCHOR BOLT IRREGULARITIES

REFERENCE: TAC Number 67908

By letter dated February 3, 1988 (BEC0 88-018) you provided the NRC staff with technical evaluations of Pilgrim fire door-to-frame and frame-to-wall gaps, as well as fire door frame anchor bolting irregularities. The evaluations establish acceptance criteria to ensure the doors provide the required fire protection, which was a subject of our fire protection meeting with your staff on November 24, 1987.

We have completed our review of your submittal and find that your evaluation and acceptance criteria are adequate to ensure that the required fire protection will be provided. We therefore consider this item and TAC 67908 closed.

We have enclosed a copy of our Safety Evaluation for your information.

Sincerely,

Original signed by:

Daniel G. McDonald, Senior Project Manager
Project Directorate I-3
Division of Reactor Projects I/II

Enclosure:
Safety Evaluation

cc: w/enclosures:
See next page

DDM 5/13/88 *See previous concurrence

OFC	: PD-3 *	: PDI-3 *	: PDI-3	: PDI-3	: PDI-3/DIR	:	:
NAME	: <i>[Signature]</i>	: <i>[Signature]</i>	: <i>[Signature]</i>	: <i>[Signature]</i>	: <i>[Signature]</i>	:	:
	: <i>[Signature]</i>	: <i>[Signature]</i>	: <i>[Signature]</i>	: <i>[Signature]</i>	: <i>[Signature]</i>	:	:
DATE	: 5/09/88	: 5/09/88	: 5/17/88	: 5/19/88	: 5/17/88	:	:

OFFICIAL RECORD COPY

8805270175 880517
PDR ADCCK 05000293
F PDR

Docket No.: 50-293

Mr. Ralph G. Bird
Senior Vice President - Nuclear
Boston Edison Company
800 Boylston Street
Boston, Massachusetts 02199

Dear Mr. Bird:

SUBJECT: PILGRIM SAFETY EVALUATION OF FIRE DOOR-TO-FRAME, FRAME-TO-WALL
AND ANCHOR BOLT IRREGULARITIES

REFERENCE: TAC Number 67908

By letter dated February 3, 1988 (BECO 88-018) you provided the NRC staff with technical evaluations of Pilgrim fire door-to-frame and frame-to-wall gaps, as well as fire door frame anchor bolting irregularities. The evaluations establish acceptance criteria to ensure the doors provide the required fire protection, which was a subject of our fire protection meeting with your staff on November 23, 1987.

We have completed our review of your submittal and find that your evaluation and acceptance criteria are adequate to ensure that the required fire protection will be provided. We therefore consider this item and TAC 67908 closed.

We have enclosed a copy of our Safety Evaluation for your information.

Sincerely,

Daniel G. McDonald, Senior Project Manager
Project Directorate I-3
Division of Reactor Projects I/II

Enclosure:
Safety Evaluation

cc: w/enclosures:
See next page

OFC	: PD-3	: PDI-3	: PDI-3	: PDI-3	: PDI-3/DIR	:	:
NAME	: E. P. ...	: MRushbrook	: C McCracken	: McDonald	: RWessman	:	:
DATE	: 5/09/88	: 5/ /88	: 5/ /88	: 5/ /88	: 5/ /88	:	:

OFFICIAL RECORD COPY

Mr. Ralph G. Bird
Boston Edison Company

Pilgrim Nuclear Power Station

cc:

Mr. K. L. Highfill
Station Director
Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, Massachusetts 02360

Boston Edison Company
ATTN: Mr. Ralph G. Bird
Senior Vice President - Nuclear
800 Boylston Street
Boston, Massachusetts 02199

Resident Inspector's Office
U. S. Nuclear Regulatory Commission
Post Office Box 867
Plymouth, Massachusetts 02360

Mr. Richard N. Swanson, Manager
Nuclear Engineering Department
Boston Edison Company
25 Braintree Hill Park
Braintree, Massachusetts 02184

Chairman, Board of Selectmen
11 Lincoln Street
Plymouth, Massachusetts 02360

Ms. Elaine D. Robinson
Nuclear Information Manager
Pilgrim Nuclear Power Station
RFD #1, Rocky Hill Road
Plymouth, Massachusetts 02360

Office of the Commissioner
Massachusetts Department of
Environmental Quality Engineering
One Winter Street
Boston, Massachusetts 02108

Charles V. Berry
Secretary of Public Safety
Executive Office of Public Safety
One Ashburton Place
Boston, Massachusetts 02108

Office of the Attorney General
1 Ashburton Place
20th Floor
Boston, Massachusetts 02108

Mr. Robert M. Hallisey, Director
Radiation Control Program
Massachusetts Department of
Public Health
150 Tremont Street, 2nd Floor
Boston, Massachusetts 02111

Regional Administrator, Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406

Mr. James D. Keyes
Regulatory Affairs and Programs Group
Leader
Boston Edison Company
25 Braintree Hill Park
Braintree, Massachusetts 02184