Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

## Gentlemen:

This refers to the routine safety inspection of inservice inspection and plant modification activities conducted by Mr. K. D. Ward of this office on March 21-22, April 6-7, May 11-12, June 8-10, 21-22, July 6-7, 11-13, 19-21, 26-28, August 3-4, 16, 22-24, 30-31, and September 7-8, 1988, of activities at Davis-Besse Nuclear Power Station, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. P. Hildebrandt at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief Engineering Branch

Enclosure: Inspection Report No. 50-346/88009(DRS)

See Attached Distribution

RIII DITH Ward/jk 09/15/88 8809230279 880915 PDR ADOCK 05000346

RWD DeFayette 09/15/88

Danielson 09//5/88

## Distribution

cc w/enclosure:
L. Storz, Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert M. Quillin, Ohio
Department of Health
State of Ohio, Public
Utilities Commission