



Log # TXX-88710
File # 10110
903.8
Ref. # 10CFR50.55(e)

September 30, 1988

William G. Council
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
SEISMIC GAP
SDAR: CP-85-27 (SUPPLEMENTAL REPORT)

Gentlemen:

On December 17, 1985, TU Electric letter logged TXX-4650 provided notification that the deficiency involving the seismic gap between structures was reportable under the provisions of 10CFR50.55(e). The latest report on this issue, logged TXX-88434, was submitted June 28, 1988. This report is submitted to update the corrective action completion schedule.

TXX-88434 indicated that the Unit 1 corrective actions for this issue would be completed by October 1, 1988. This activity has been rescheduled for completion by February 23, 1989. The schedule for Unit 2 remains unchanged.

Very truly yours,

W. G. Council

By: John W. Beck
John W. Beck
Vice President,
Nuclear Engineering

CBC/gj

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8810030229 880930
PDR ADDCK 05000445
S PDC