DCS No: 50293880527 Date: May 27, 1988

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE--PNO-I-88-58

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region I staff on this date.

Facility:	Licensee Emergency Classification:
Boston Edison Company	Notification of Unusual Event
Pilgrim Nuclear Power Station	Alert
Boston, Massachusetts	Site Area Emergency
Docket Number 50-293	General Emergency
	X Not Applicable

Subject: MAINTENANCE WORK RESTRICTED BY LICENSEE MANAGEMENT

On the afternoon of May 27, 1988, Boston Edison management halted performance of general maintenance at Pilgrim. A licensee self-assessment completed on May 26 identified maintenance program weaknesses. Concerns regarding the effectiveness of the licensee's program for control of routine and corrective maintenance were raised by the NRC during a recent maintenance team inspection completed on May 5, as documented in a report issued May 25. In addition, the licensee's Quality Assurance department recently identified similar concerns in the area of maintenance on environmentally qualified equipment. Licensee management has concluded that significant changes to the station maintenance program are warranted, and is developing an action plan to address the problem. All maintenance tasks which are not covered by job-specific, detailed, approved station procedures have been suspended pending review. Activities such as surveillance testing and a small number of maintenance activities, that are clearly delineated by detailed procedures, will be allowed to continue. Additional maintenance tasks are being reviewed on a case-by-case basis and will only be released to the field if appropriate procedures or instructions are written and applied. All work released, will be reviewed and approved by the Maintenance Section Manager. The resident inspectors are monitoring licensee actions.

No offsite notifications were made by the licensee.

Region I is prepared to respond to media inquiries.

The Commonwealth of Massachusetts has been informed.

CONTACT: J. Lvash D. Haverkamp

(617)	747-0565	(215) 337-5120			
DISTRIBUTION: OWFN Chairman Zech	MNBB AEOD	H-St. ACRS	NL RES	Mail:	
Comm. Roberts	ARM	PDR	KES		DOT: Trans only
Comm. Bernthal	OGC			NRC Op	s Ctr
Comm. Carr			71100		
Comm. Rogers SECY NMSS			INPO		
CA NRR			NOAC		
OGC OIA	Regiona	1 Offices			
GPA OI			RI Reside	ent Offi	ce
PA SLITP					
EDO OE			Licensee		or Licensees)
Region I Form 83				(React	or Licensees)
region 1 form 00	8806	060158 880527			

(Rev. April 1988)

FDR I&E PNO-I-88-058 DCD TE-34/1