Docket No. 50-333

Power Authority of the State of New York James A. FitzPatrick Nuclear Power Plant ATTN: Mr. Radford J. Converse Resident Manager P. O. Box 41 Lycoming, New York 13093

Gentlemen:

Subject: Inspection Report 50-333/88-16

A followup inspection was conducted on August 9-12, 1988 to complete the review of your corrective and preventive actions documented in your May 20, and May 21, 1987 letters. In addition, your planning and preparations for the refueling outage including radiological controls were also examined during this inspection. The radiological controls planning and preparations were found to be adequate to support the outage.

No violations were identified during this inspection and no reply to this letter is required.

Your cooperation with us in this matter is appreciated.

Sincerely,

Renald R. Bellamy
Renald R. Bellamy
Renald R. Bellamy, Chief
Facilities Radiological Safety
and Safeguards Branch
Division of Radiation Safety
and Safeguards

Enclosure: NRC Region I Inspection Report No. 50-333/88-16

cc w/encl: J. Phillip Bayne, President Mr. Join C. Brons, Executive Vice President A. Klausmann, Senior Vice President - Appraisal and Compliance Services R. L. Patch, Quality Assurance Superintendent George M. Wilverding, Manager Nuclear Safety Evaluation Gerald C. Goldstein, Assistant General Counsel R. E. Beedle, Vice President Nuclear Support S. S. Zulla, Vice President Nuclear Engineering R. Burns, Vice President Nuclear Operation Dept. of Public Service. State of New York State of New York, Department of Law Licensing Project Manager, NRR Public Document Room (PDR) Local Public Document Room (LPDR) Nuclear Safety Information Center (NSIC) NRC Resident Inspector State of New York

bcc w/enc1:
Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o enc1)
Section Chief, DRP
Robert J. Bores, DRSS
B. Clayton, EDO

RI:DRSS Thomas/mk/s/9/ RI:DRSS Shanbaky 09//9/88 OFFICIAL RECORD COPY RI:DRSS Bellamy

09/20/88
IR POWER AUTHORITY 88-16 - 0002.0.0
08/30/88