



Log # TXX-88696
File # 10110
903.5
Ref. # 10CFR50.55(e)

William G. Council
Executive Vice President

September 26, 1988

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
SERVICE WATER DISCHARGE PIPE MISSILE PROTECTION
SDAR: CP-88-22 (SUPPLEMENTAL REPORT)


Gentlemen:

On February 5, 1988, TU Electric final report logged TXX-88186 notified the NRC Staff of a reportable deficiency involving service water discharge pipe missile protection. This supplemental report is submitted to provide the current status of this issue.

TXX-88186 indicated that Unit 1 and 2 corrective actions would be completed by September 16, 1988. However, TU Electric is currently performing a detailed reevaluation of this issue and the previously specified corrective action. A summary of the reevaluation and any changes to the corrective action will be provided no later than November 15, 1988.

Very truly yours,

W. G. Council

By: 
R. D. Walker
Manager, Nuclear Licensing

HAM/mlh

c - Mr. R. D. Martin, Region IV
Resident Inspectors CPSES (3)

8810040147 880926
PDR ADOCK 05000445
S PDC

IE27
110