

MAY 25 1988

Official

Docket Nos. 50-348, 50-364
License Nos. NPF-2 and NPF-8

Alabama Power Company
ATTN: Mr. R. P. McDonald
Senior Vice President
P. O. Box 2641
Birmingham, AL 35291-0400

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-348/88-15 AND 50-364/88-15

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by W. H. Bradford on April 11 thru May 10, 1988. The inspection included a review of activities authorized for your Farley facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is directed to the unresolved item identified in the inspection report. This matter will be pursued during future inspection.

In accordance with Section of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

S
David M. Verrelli, Chief
Reactor Projects Branch 1
Division of Reactor Projects

Enclosure: (See page 2)

MAY 25 1988

Alabama Power Company

2

Enclosure:
NRC Inspection Report

cc w/encl:
B. M. Guthrie, Executive Vice President
J. D. Woodard, General Manager -
Nuclear Plant
W. G. Hairston, III, Vice President -
Nuclear Support
J. W. McGowan, Manager-Safety Audit
and Engineering Review
S. Fulmer, Supervisor-Safety
Audit and Engineering Review

bcc w/encl:
NRC Resident Inspector
DRS Technical Assistant
E. Reeves, Project Manager, NRR
Document Control Desk
State of Alabama

R11
LM
LModeros:ser
05/25/88

R11
HD
HDance
05/25/88