Docket No. 50-456 Docket No. 50-457

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

Based on the September 1, 1988, telephone conversation between Ms. Laurie Literski of the Braidwood Nuclear Generating Station and Mr. Gary Shear of my staff, it is my understanding that September 22, 1988, was agreed upon as the date for Mr. Shear's site visit to tour the emergency response facilities of the Braidwood Nuclear Generating Station.

Recent experience in the Federal Field Exercise identified the need for Region III to evaluate each licensee's emergency response facilities to determine if the NRC's Expanded Activation Site Team can be adequately accommodated. IE Information Notice No. 86-18 described the planned composition and location of the NRC Site Team that would respond to a major nuclear power plant accident.

Region III does not expect licensees to backfit to provide increased facility space. Facilities that have been constructed and approved under current regulations and guidance may not have the capability to accommodate the NRC Expanded Site Team as outlined in Information Notice 86-18.

Our goal is to consider with each licensee, ways of making more efficient use of available space, of providing adequate communications, and of identifying alternate space where relevant data could be made available in a timely, reliable manner.

Attached to this letter is an outline of the areas we will be reviewing. If there are questions regarding any of the above, please contact Gary Shear at (312) 790-5620.


Sincerely,

pien far

W. D. Shafer, Chief Emergency Preparedness and Radiological Protection Branch

Attachment: As stated







Commonwealth Edison Company

2 SEP 0 8 1988

Distribution

cc w/enclosure: T. J. Maiman, Vice President, PWR Operations H. Bliss, Nuclear Licensing Manager S. Hunsader, Nuclear Licensing Administrator M. Lohmann, Project Construction and Startup Superintendent R. E. Querio, Station Manager P. L. Barnes, Regulatory Assurance Supervisor DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Braidwood Resident Inspector, RIII Byron D. W. Cassel, Jr., Esq. H. S. Taylor, Quality Assurance Division E. Chan, OGC G. Berry, OGC Stephen P. Sands, NRR Laurie Literski, CECo John Golden, CECo Bob Hajec, CECo

ATTACHMENT

.

51

OUTLINE FOR EVALUATING LICENSEE ACCOMMODATIONS FOR NRC SITE TEAM

I. Communications

- A. Telephone Capabilities
 - 1. Number of Available Phones
 - 2. Location of Available Phones
 - 3. Type of Phone Service (e.g., voice activated)
- II. Size and Layout of TSC and EOF
 - A. Space Availability for Expanded Site Team
 - B. Seating and Desk Arrangements for Expanded Site Team
 - C. Location of Key Counterpart Licensee Personnel
 - D. Conferencing Spacing for NRC Personnel

III. Alternate Space