

CP&L

Carolina Power & Light Company

~~ADMITTED~~ MAR 2 4 17 PM '86
Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
March 26, 1986

FILE: B09-13510C
SERIAL: BSEP/86-0347


Dr. J. Nelson Grace, Administrator
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street NW
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-86-002)

Dear Dr. Grace:

On February 19, 1986, at 1000, a Unit 1 fire barrier LCO was initiated on penetration seal No. CB-2-301, fire door 221. This door, which is located on the 49-foot elevation of the Unit 1 Control Building, provides personnel access to the Unit 1 computer room from the Control Room. The LCO was initiated to permit opening the door to allow ambient air circulation between the computer room and the Unit 1 Control Room electronic equipment area due to the inoperability of the computer room air-conditioning unit. Required repairs to the subject air-conditioning unit were completed and on February 26, 1986, at 2000, the LCO was canceled and door 221 was returned to service.

Very truly yours,



C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/mcg

Enclosure

cc: NRC Document Control Desk

8604100051 860326
PDR ADOCK 05000325
A PNP

IEZ
1/0
ETT