



Log # TXX-88700
File # 10110
903.7
Ref. # 10CFR50.55(e)

William G. Council
Executive Vice President

September 28, 1988

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
SEISMIC ANALYSIS OF SERVICE WATER INTAKE STRUCTURE
SDAR: CP-87-115 (SUPPLEMENTAL REPORT)

Gentlemen:

On February 4, 1988, TU Electric letter logged TXX-88055 provided notification of a reportable deficiency involving a modeling error for seismic analysis of the service water intake structure. A similar problem was noted for seismic Category I concrete tanks. This report is submitted to provide the current status of this issue.

TXX-88055 indicated that Unit 1 corrective actions would be completed by September 28, 1988. The completion date of September 28, 1988 was not met. TU Electric's next report regarding the status of the corrective action completion dates for this issue will be submitted no later than November 30, 1988.

Very truly yours,

W.G. Council

W. G. Council

By:

D.R. Woodlan

D. R. Woodlan
Docket Licensing Manager

CBC/mlh

c-Mr. R. D. Martin, Region IV
Resident Inspectors CPSES (3)

8810060088 880928
PDR ADOCK 05000445
S PDC

1-127
1/0