
VERMONT YANKEE NUCLEAR POWER CORPORATION



RD 5, Box 169, Ferry Road, Brattleboro, VT 05301

FVY 88-83

ENGINEERING OFFICE

1671 WORCESTER ROAD
FRAMINGHAM MASSACHUSETTS 01701

TELEPHONE 517-872-8100

September 27, 1988

U.S. Nuclear Regulatory Commission Washington, D.C. 20655

Attn:

Document Control Desk

References:

a) License No. DPR-28 (Docket No. 50-271)

b) Letter, USNRC to VYNPC, NVY 88-160, Inspection Report

No. 50-271/88-200, dated 8/10/88

Dear Sir:

Subject:

Vermont Yankee Response to Inspection Report No. 50-271/88-200, Emergency Operating Procedure (EOP) Inspection

As a result of the Emergency Operating Procedure (EOP) inspection conducted at our facility during the period June 1-10, 1988, Reference b) requested that we provide you with our schedule for providing additional information related to our EOP's. This request is based on an observation that the documents that support the differences between the generic, NRC-accepted Emergency Procedure

review.

As noted in the inspection report, we had conducted an independent assessment prior to the NRC inspection and identified several areas where enhancements could be made to our EOP-related documents. To address the issue in an efficient and effective manner, it is our plan to resolve all open issues related to both the independent audit and the NRC inspection and, in parallel, update the PGP, including the PSTG's with justification for deviations from EPG, Revision 3. The resubmittal of these items as requested in Reference b) will be made by March 31, 1989. The schedule for this effort is not tied to NRC issuance of a generic safety evaluation report for Revision 4 of the EPG's.

Guidelines (EPG) and our EOP's had not been formally transmitted to the NRC for

Should you have any questions or desira any additional information on this issue, please do not hesitate to contact us.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

Warren P. Murphy Vice President and

Manager of Operations

an ommun

/dm

cc: USNRC Regional Administrator, Region I USNRC Resident Inspector, VYNPS

8810060151 880927 PDR ADOCK 05000271 IE35