



Northern States Power Company

Prairie Island Nuclear Generating Plant

1717 Wakonade Dr. East
Welch, Minnesota 55089

October 26, 1998

10 CFR Part 50
Section 50.73

U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT

Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

**LER 1-98-14
Supplement 1**

Fire Area 32 Appendix R Safe Shutdown Analysis Issues

Supplement 1 to the Licensee Event Report (LER) for this occurrence is included as Attachment 1 to this letter. In the report, we made no new NRC commitments.

For your information, we have included a copy of the detailed Safety Significance evaluation for this event as Attachment 2 to this letter. The conclusions of this evaluation are summarized in the Analysis section of the LER. This fulfills one commitment from the original submittal of the LER. Please note that the probabilistic arguments, also contained in the Analysis section, remain relevant to this event.

This event was reported via the Emergency Notification System in accordance with 10CFR Part 50, Section 50.72, on August 27, 1998.

Please contact us if you require additional information related to this event.

Joel P. Sorensen
Plant Manager
Prairie Island Nuclear Generating Plant

IE221

9810300159 981026
PDR ADOCK 03000282
S PDR

000045

c: Regional Administrator - Region III, NRC
NRR Project Manager, NRC
Senior Resident Inspector, NRC
Kris Sanda, State of Minnesota

Attachments:

1. Licensee Event Report 1-98-14, Supplement 1, "Fire Area 32 Appendix R Safe Shutdown Analysis Issues."
2. Deterministic Evaluation of Safety Significance of Loss of 12 MDAFW Pump Due to Fire Induced Spurious Closure of the Condensate Supply Motor Operated Valve.

Attachment 1

Licensee Event Report 1-98-14

Supplement 1

Fire Area 32 Appendix R Safe Shutdown Analysis Issues