

BOSTON EDISON

Pilgrim Nuclear Power Station Rocky Hill Road Plymouth, Massachusetts 02360

Ralph G. 3ird Senior Vice President — Nuclear

> October 4, 1988 BECo Letter #88-141

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

> Docket No: 50-293 License No: DPR-35

Subject: Boston Edison Company Report on the Status of Offsite Emergency Preparedness Around Pilgrim Nuclear Power Station

Dear Sir:

Enclosed is Boston Edison's response to the NRC's letter of September 26, 1988 entitled "Offsite Emergency Preparedness -Pilgrim Nuclear Power Station (PNPS)". This written description reflects Boston Edison's understanding of Pilgrim offsite emergency plans, implementing procedures, training, and the status of the six issues identified by the Federal Emergency Management Agency in August 1987.

Please contact either Ron Varley, Manager of Emergency Preparedness or myself with any questions or comments.

Bird G:

/Attachment

810070

October 4, 1988 BECo Ltr. #88-141 Page 2

۱

١

Docket No.: 50-293 License No.: DPR-35

t

ø

cc: Mr. William T. Russell Regional Administrator U.S. Nuclear Regulatory Commission - Region I 475 Allendale Road King of Prussia, PA 19406

Mr. D. G. McDonald Project Manager Division of Reactor Projects I/II U.S. Nuclear Regulatory Commission Mail Stop #14D1 One White Flint North 11555 Rockville Pike Rockville, MD 20852

Senior NRC Resident Inspector Pilgrim Nuclear Power Station