Docket No. 50-62 License No. R-66

University of Virginia ATTN: Dr. R. U. Mulder, Director Reactor Facility Charlottesville, VA 22901

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-62/88-03

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by G. B. Kuzo on August 22-25, 1988. The inspection included a review of activities authorized for your University of Virginia Pool Reactor. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original Signed By D. M. Collins

Douglas M. Collins, Chief Emergency Preparedness and Radiological Protection Branch Division of Radiation Safety and Safeguards

Enclosure: (See page 2)

B810120263 BB0929 PDR ADOCK 05000062

IEO G

Enclosure: Inspection Report

cc w/encl:
Dr. J. S. Tulenko, University
of Florida
Dr. Ratib A. Karam, Georgia
Institute of Technology
Dr. Paul J. Turinsky, North
Carolina State University
Commonwealth of Virginia

bcc w/o encl: License Fee Management Branch DRS Technical Assistant

bcc w/encl:
Document Control Desk

RII GKU20 94,8/88 CHosey 908/88

PFredrickson 9/3/88