Docket No. 50-456, 50-457

Mr. Henry E. Bliss Nuclear Licensing Manager Commonwealth Edison Company P.O. Box 767 Chicago, Illinois 60690

Dear Mr. Bliss:

By letters dated August 26 and September 2, 1988, Commonwealth Edison Company submitted a proposal for NRC to review the performance of mixed-grease samples with mixtures of 12% of 33% of Sun EP50 mixed with Exxon Nebula EP0/EP1.

The NRC staff has completed its review of your submittal as to whether mixed grease with greater than 5% contaminant will affect the operability of Limitorque valve operators in the Braidwood Station, Units 1 and 2. The NRC staff has concluded that there is insufficient information to make a determination on the post accident operability of these Limitorque valve operators. Therefore, Braidwood Units 1 and 2 valves with greater than 5% grease contaminant in operators may not have been able to perform their intended function following the environmental exposure to a Design Basis Accident. Our Safety Evaluation is enclosed.

Sincerely,

15

Stephen P. Sands, Project Manager Project Directorate III-2 Division of Reactor Projects - III, IV, V and Special Projects

Enclosure: As stated

cc: See next page

DISTRIBUTION
Docket file S
NRC & Local PDRs O
PDIII-2 r/f E
GHola'ian B
MVirgilio A
Lluther P

SSands OGC EJordan BGrimes ACRS (10) Plant file

OFO!

SSands: km 10/6/88

PDIIII-241 LLuther 10/06/88

PDIII-2 DMuller 10/6/88

8810130170 881004 PDR ADOCK 05000456 PDC



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D. C. 20535 October 6, 1988

Docket No. 50-456, 50-457

Mr. Henry E. Bliss Nuclear Licensing Manager Commonwealth Edison Company P.O. Box 767 Chicago, Illinois 60690

Dear Mr. Bliss:

By letters dated August 26 and September 2, 1988, Commonwealth Edison Company submitted a proposal for NRC to review the performance of mixed-grease samples with mixtures of 12% of 33% of Sun EP50 mixed with Exxon Nebula EP0/EP1.

The NRC staff has completed its review of your submittal as to whether mixed grease with greater than 5% contaminant will affect the operability of Limitorque valve operators in the Braidwood Station, Units 1 and 2. The NRC staff has concluded that there is insufficient information to make a determination on the post accident operability of these Limitorque valve operators. Therefore, Braidwood Units 1 and 2 valves with greater than 5% grease contaminant in operators may not have been able to perform their intended function following the environmental exposure to a Design Basis Accident. Our Safety Evaluation is enclosed.

Sincerely,

Stephen P. Sands, Project Manager

Project Directorate III-2

Division of Reactor Projects - III.
IV. V and Special Projects

Enclosure: As stated

cc: See next page

Mr. Henry E. Bliss Commonwealth Edison Company

CC:

Mr. William Kurtier Atomic Power Distribution Westinghouse Electric Corporation Post Office Box 355 Pittsburgh, Pennsylvania 15230

Joseph Gallo, Esq. Hopkins and Sutter 1050 Connecticut Ave., N. W. Suite 1250 Washington, D. C. 20036

C. Allen Bock, Esq. Post Offices Box 342 Urbana, Illinois 61801

Ms. Bridget Little Rorem Appleseed Coordinator 117 North Linden Street Essex, Illinois 60935

Mr. Edward R. Crass
Nuclear Safeguards and
Licensing Division
Sargent & Lundy Engineers
55 East Monroe Street
Chicago, Illinois 60603

U. S. Nuclear Regulatory Commission Resident Inspectors Office RR#1, 50x 79 Brace 'le, Illinois 60407

Regional Administrator, Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road, Bldg. #4 Glen Ellyn, Illinois 60137

Chairman Will County Board of Supervisors Will County Board Courthouse Joliet, Illinois 50434 Braidwood Station Units 1 and 2

Ms. Lorraine Creek Route 1, Box 182 Manteno, Illinois 60950

Douglass Cassel, Esq. 109 N. Dearborn Street Chicago, Illinois 60602

Elena Z. Kezelis, Esq. Isham, Lincoln & Beale Three First National Plaza Suite 5200 Chicago, Illinois 60602

Mr. Charles D. Jones, Director Illinois Emergency Services and Disaster Agency 110 East Adams Street Springfield, Illinois 62706

Michael Miller, Esq. Sidley and Austin One First National Plaza Chicago, Illinois 60603

George L. Edgar Newman & Holtzinger, P.C. 1615 L Street, N.W. Washington, D.C. 20036

Attorney General
500 South 2nd Street
Springfield, Illinois 62701

EIS Review Coordinator EPA Region V 230 S. Dearborn Street Chicago, Illinois 60604