



An Illinova Company

Illinois Power Company
Clinton Power Station
P.O. Box 678
Clinton, IL 61727
Tel 217 935-5700
Fax 217 935-4632

Walter G. MacFarland IV
Senior Vice President
and Chief Nuclear Officer

U-603100

2C.220

October 30, 1998

Docket No. 50-461

10CFR50.73

Document Control Desk
Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Clinton Power Station - Unit 1
Licensee Event Report No. 1998-034-00

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-034-00: Inattention to Detail During Performance of Design Change Causes One Train of Suppression Pool Cooling Mode of Residual Heat Removal System to be Outside of Its Design Basis. This report is being submitted in accordance with the requirements of 10CFR50.73. A revision to this LER containing additional corrective actions is expected to be submitted by December 15, 1998.

The enclosed report contains the following commitments:

- A modification will be installed to allow the circuit breaker for valve 1E12-F006B to be open without affecting the operation of 1E12-F024B. This modification will be installed prior to startup from the current outage.

Sincerely yours,

Walter G. MacFarland, IV
Senior Vice President and
Chief Nuclear Officer

9811090072 981030
PDR ADOCK 05000461
S PDR

MRS/krk

Enclosure

cc: NRC Clinton Licensing Project Manager
NRC Resident Office, V-690
Acting Regional Administrator, Region III, USNRC
Illinois Department of Nuclear Safety
INPO Records Center

IE22/1