4e//on

JUN 0 1 1988

Docket Nos. 50-348, 50-364 License Nos. NPF-2 and NPF-8

Alabama Power Company ATTN: Mr. R. P. McDonald Senior Vice President P. O. Box 2641 Birmingham, AL 35291-0400

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-348/88-17 AND 50-364/88-17

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by G. A. Hallstrom on May 2-6, 1988. The inspection included a review of activities authorized for your Farley facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Alan R. Herdt, Chief Engineering Branch

Division of Reactor Safety

Enclosure: NRC Inspection Report

cc: (See page 2)

8806200359 880601 PDR ADOCK 05000348 D DCD 1/1

cc w/encl:

B. M. Guthrie, Executive Vice President J. D. Woodard, General Manager -

Nuclear Plant

W. G. Hairston, III, Vice President -

Nuclear Support

J. W. McGowan, Manager-Safety Audit

and Engineering Review

S. Fulmer, Supervisor-Safety Audit and Engineering Review

bcc w/encl: NRC Resident Inspector DRS Technical Assistant E. Reeves, Project Manager, NRR Document Control Desk State of Alabama

GHallstrom:ser 05/18/88

HOD **HDance** 05/31/88