



Log # TXX-88748  
File # 10110  
908.3  
Ref. # 10CFR50.55(e)

October 20, 1988

William G. Counsil  
Executive Vice President

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
DOCKET NOS. 50-445 AND 50-446  
LOSS OF CONTROL POWER INDICATION  
SDAR: CP-87-128 (SUPPLEMENTAL REPORT)

Gentlemen:

On January 6, 1988, we notified you of a deficiency involving the emergency diesel generator auto start circuitry loss of control power indication. Our last report on this issue was logged TXX-88274, dated March 7, 1988. The purpose of this report is advise you that we are reevaluating this issue.

Upon completion of our reevaluation, we will advise you of any changes to our submittal. Our next report will be submitted no later than March 10, 1989.

Very truly yours,

*W. G. Counsil*

W. G. Counsil

By: *J. S. Marshall*  
J. S. Marshall  
Generic Licensing Manager

VPC/gj

c - Mr. R. D. Martin, Region IV  
Resident Inspectors, CPSES (3)

BB10250469 881020  
PDR ADOCK 05000445  
S PNU