DMB



Commonwealth Edison LaSalle County Nuclear Station Rural Route #1, Box 220 Marseilles, Illinois 61341 Telephone 815/357-6761

non

TORITY ROUTING FILERAS

May 15, 1986

50-373

MAY 1 9 1986

TEOI

Mr. James G. Keppler Regional Administrator Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Sir:

This special report is submitted in accordance with LaSalle Unit 1 Operating License NPF-11, Appendix A, and LaSalle Unit 2 Operating License NPF-18, Appendix A, Technical Specifications 3.7.5.2 and 3.7.5.4.

On April 1, 1986, at 1800 hours the Unit 1 Cable Spreading Room sprinkler system and hose stations FB250, FB155, FB248, FB191 and FB157 were removed from service to permit construction activities required for the completion of design Modification M-1-1-85-047. This Modification is required by Unit 2 (NPF-18) License Condition 2.C.(15)(e).

It is expected that construction activities will continue for one month. In any case, the Unit 1 Cable Spreading Room Sprinkler System will be returned to service prior to restarting Unit 1 from the first refueling outage. The fire hose stations were returned to service on April 25, 1986.

To assure that the level of fire protection is not decreased during the course of this Modification, LaSalle will meet the requirements of Action Statements "a" of Technical Specifications 3.7.5.2 and 3.7.5.4 by establishing a fire watch with backup fire suppression equipment in the affected area or routing additional fire hose of equal or greater diameter to the unprotected areas from operable hose stations as appropriate.

for G. J. Diederich

G. J. Diederich Station Manager LaSalle County Station

GJD/DJR/kg

xc: U.S. NRC Document Control Desk INPO-Records Center File/NRC

8605270186 860515 PDR ADOCK 05000373 S PDR