

Union Electric

One America Plaza
1901 Chouteau Avenue
PO Box 66149
St. Louis, MO 63166-6149
314.621.3222

November 13, 1998

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555-0001

Gentlemen:

ULNRC- 03920
TAC No. MA3954




CALLAWAY PLANT
DOCKET NUMBER 50-483
REVISION TO TECHNICAL SPECIFICATION 3/4 .4
REACTOR COOLANT SYSTEM

Reference: ULNRC-3910 dated October 27, 1998

The reference letter transmitted an amendment request that superseded an existing request regarding the use of steam generator tube electrosleeve repair process. The reference letter transmitted a proprietary version of Framatome Technologies, Inc. topical report BAW-10219P, Revision 3. Attached is the non-proprietary version of this report for handling under the provisions of 10CFR2.790.

If you have questions concerning this matter please contact us.

Sincerely,

for 
Alan C. Passwater
Manager, Corporate Nuclear Services

1/1

DS/jdg

9811180126 981113
PDR ADOCK 05000483
P PDR

cc: M. H. Fletcher
Professional Nuclear Consulting, Inc.
19041 Raines Drive
Derwood, MD 20855-2432

Regional Administrator *w/a*
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 400
Arlington, TX 76011-8064

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. Mel Gray (2)
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
1 White Flint, North, Mail Stop 13E16
11555 Rockville Pike
Rockville, MD 20852-2738

Manager, Electric Department
Missouri Public Service Commission
P.O. Box 360
Jefferson City, MO 65102

Nuclear Energy Institute
1776 I Street N.W.
Suite 400
Washington, DC 20006-3708