In Reply Refer To: Docket: STN 50-482/88-24

Wolf Creek Nuclear Operating Corporation ATTN: Bart D. Withers President and Chief Executive Officer P.O. Box 411 Burlington, Kansas 66839

Gentlemen:

This refers to the inspection conducted by Messrs. B. L. Bartlett and M. E. Skow of this office during the period September 1-30, 1988, of act: ies authorized by NRC Operating License No. NPF-42 for the Wolf Creek Generat. Station, and to the discussion of our findings with Mr. G. D. Boyer and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection included plant status, followup on a previously identified NRC item, review of licensee event reports, operational safety verification, monthly surveillance observation, monthly maintenance observation, onsite event followup, preparation for refueling, physical security verification, and radiological protection. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspectors. The inspection findings are documented in the enclosed inspection report.

During this inspection, it was found that certain of your activities were in violation of NRC requirements. Consequently, you are required to respond to these violations, in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

We have also examined actions you have taken with regard to a previously identified inspection finding. The status of this item is identified in paragraph 3 of the enclosed report.

SOCFA RIV:PSA MESKOW 10/27/88

PSA dlBartlett

PSA FO ATHOWell (0 /2 788 C:PSA DDChanberlain /1 /27/88

D: DRP into Lucalian 10/2 5/88

工艺

The response directed by this letter and the accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

L. J. Callan, Director Division of Reactor Projects

Enclosures:

 Appendix A - Notice of Violation
Appendix B - NRC Inspection Report 50-482/88-24

cc w/enclosures: Otto L. Maynard, Manager of Licensing Wolf Creek Nuclear Operating Corporation P.O. Box 411 Burlington, Kansas 66839

Gary Boyer, Plant Manager Wolf Creek Nuclear Operating Corporation P.O. Box 411 Burlington, Kansas 66839

Mr. Robert D. Elliott, Chief Engineer Kansas Corporation Commission Fourth Floor, Docking State Office Bldg. Topeka, Kansas 66612-1571

Kansas Radiation Control Program Director

bcc to DMB (IEO1) bcc distrib. by RIV: *DRP Myron Karman, ELD, MNBB (1) *RRI R. D. Martin, RA DRP *Section Chief, (PS/A) *RSPB-DRSS J. M. Hinds, RIII *RIV File Callaway RRI, RIII *Project Engineer, DRP/A DRS *MIS System *RSTS Operator *L. Shea, RM/ALF D. Picket, NRR PM *w/766